

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 16 and 21

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1638)

Set stone 16 x 12 x 5, 8" in ground, for the 1/4 sec. corner, from which
A Fir 14" dia., bears N.30°E., 28 lks. dist.
A Maple 12" dia., bears S.15°E., 8 lks. dist.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1716) (and duplicated info. on Page 1722)

A Stone 10 x 10 x 6" above ground, marked 1/4 S on the N. face, from which,
A Fir 18" dia., bears N.20°E., 29 lks. dist., mkd. 1/4 S BT.
The other BT destroyed, I marked:
A Fir 6" dia., bears S.7°E., 28 lks. dist. mkd. 1/4 S BT.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16059-60)

The 1/4 sec. cor., determined from the remains of the original bearing trees:

A Fir stump 32" dia., bears N.23 1/2°E., 29 lks. dist., with scribe marks BT visible on opened blaze. (Rec. N.20°E.)
A Maple 26" dia., bears S.15°E., 8 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W
1/4 S 16
S 21
1975

from which new bearing trees:

A Fir 10" dia., bears N.38 1/2°E., 30 lks. dist. mkd. 1/4 S16 BT.
A Hemlock 31" dia., bears S.26 3/4°W., 52 lks. dist. mkd. 1/4 S21 BT.

Corner is located on top of spur, slopes N.10°W.

Cor. Fd. and used in BLM resurvey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 - (DCSO records, Vol. 47 Page 17940)