

PRIMARY CORNER DESCRIPTION Sec. cor. for 21, 22, 27 and 28

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1637)

-----  
Set a sandstone 20 x 16 x 8, for corner to secs. 21, 22, 27 and 28, 12" in ground, on steep hillside. No trees.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1691 (and duplicated on pages 1710-11))


-----  
Could not find corner, I therefore,  
Set sandstone 20 x 14 x 6 ins., 16" in the ground, on steep hillside sloping East, for cor. to secs. 21, 22, 27 and 28, mkd. with 2 notches on the S., and 3 notches on the E. sides, from which  
A dead Fir 30" dia., bears N.22°E., 8 lks. dist. mkd. T22S R9W S22 BT.  
A Dogwood 6" dia., bears S.61°E., 107 lks. dist. mkd. T22S R9W S27 BT.  
A dead Fir 36" dia., bears S.74°W., 80 lks. dist. mkd. T22S R9W S28 BT.  
A dead Fir 24" dia., bears N.40°W., 61 lks. dist. mkd. T22S R9W S21 BT.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16046)

-----  
The sec. cor., monumented with the original sandstone, 20 x 14 x 6 ins., firmly set 10" in the ground, mkd. with 3 grooves on E. and 2 grooves on S. faces, from which the remains of an original bearing tree:

A decayed Fir stump, size indeterminate, bears N.22°E., 8 lks. dist., no marks visible.

At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:



from which new bearing trees:  
A Maple 22" dia., bears N.28½°E., 66 lks. dist. mkd. T22S R9W S22 BT.  
A Fir 27" dia., bears S.37 3/4°E., 60 lks. dist. mkd. T22S R9W S27 BT.  
(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec. cor. for 21, 22, 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 18" dia., bears S.47¼°W., 15 lks. dist. mkd. T22S  
R9W S28 BT.  
A Fir 30" dia., bears N.29½°W., 83 lks. dist. mkd. T22S  
R9W S21 BT.  
Deposit corner stone alongside iron post.

Cor. Fd. and used in BLM resurvey by Malloy and Farnsworth,  
under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 (DCS0  
records, Vol. 47 Pages 17916-17)

Found OK by Neil Hibbs, 8/2025 - M185-39