

PRIMARY CORNER DESCRIPTION Sec. cor. for 10 & 15 (E. bdy. Sec. 16)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1628)

Marked a Maple 6" dia., for the cor. to secs. 9, 10, 15 and 16, from which

- A Fir 5" dia., bears N.60°E., 5 lks. dist.
- An Alder 6" dia., bears S.1°E., 37 lks. dist.
- A Maple 8" dia., bears S.45°W., 2 lks. dist.
- A Maple 6" dia., bears N.45°W., 5 lks. dist.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1662 (and Duplicated page 1709))

After diligent search, I was unable to find any evidence of the cor. to secs. 9, 10, 15 and 16.

I set sandstone 20x16x6 ins., 15" in ground in land slide on hillside sloping South for the corner to secs. 9, 10, 15 and 16, marked with 4 notches on the S., and 3 notches on the E. sides, from which

- A Cedar 10" dia., bears N.81°E., 39 lks. dist. mkd. T22S R9W S10 BT.
- A Fir 48" dia., bears S.51°E., 145 lks. dist. mkd. T22S R9W S15 BT.
- A Maple 20" dia., bears S.44°30'W., 22 lks. dist. mkd. T22S R9W S16 BT.
- A Maple 4" dia., bears N.13°W., 40 lks. dist. mkd. T22S R9W S9 BT.

I found blazing on E. and W. line corresponding with this corner.

Wilford N. Haines - June 6, 1956 - C.S. File 42/153

Found - 1½" I.Pipe with cap marked, about 2 ft. out of ground. (Also see M 34-17 for reference to cap)
Orig. BT, 24" Cedar, N.81°E., 39 lks. Poor condition. Tag on BT.

Orig. BT, Maple, S.44°30'W., no scribe. A hole in tree.
Blazed line to East.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1367, surveyed Apr/June 1987 - (DCSO records Vol. 45 Page(s) 18426)

(Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. cor. for 10 & 15 (on E. bdy S. 16)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

At the cor. of secs. 10 and 15 only, perpetuated by person(s) unknown and recorded by Haines in 1956, monumented with an iron post, 1½" dia., firmly set, projecting 24" above ground, with iron cap mkd. S10 S15 S16, from which the remains of bearing trees mkd. by Gesner and Worrick:

A Cedar 45" dia., bears N.81°E., 39 lks. dist. with old axe marks visible.

A Maple 48" dia., bears S.34½°W., 22 lks. dist., no marks remaining on open, decayed blaze. (Rec. S.44½°W.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W
16 S 10
 S 15
1987

from which new bearing trees:

A Fir 7" dia., bears N.6 3/4°E., 124 lks. dist. mkd. T22S R9W S10 BT.

A Fir 23" dia., bears S.68°E., 41 lks. dist. mkd. T22S R9W S15 BT.

Deposit a white "DEEP-1" magnetic marker at the base and local iron post alongside the corner post.

The corner is located 45 lks. N. of a creek, 1 lk. wide, course N.80°E.

Found OK by T. Rambo, Oct. 2000 - M136-12