

PRIMARY CORNER DESCRIPTION C C for Secs. 9 and 16 (W. bdy. S. 10)

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1668))

At 315 lks. North of the corner to secs. 9, 10, 11 and 16: I Set Fir post 4½ ft. long, 4" sq., 24" in the ground, at the point of intersection on hillside sloping E. for closing corner to secs. 9 and 16, marked T22S S16 on the S.; C.C. on the W.; and R9W S9 on the N. faces, with 4 grooves on the S. and 3 grooves on the E. sides, from which

A Fir 8" dia., bears N.65°E., 81 lks. dist. mkd. C.C. T22S R9W S9-16 BT.

A Fir 30" dia., bears S.40°W., 184 lks. dist. mkd. T22S R9W S16 BT.

A Fir 8" dia., bears N.21°W., 148 lks. dist. mkd. T22S R9W S9 BT.

I destroyed mark on the witness tree in sec. 9.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, and crew -June 24, 1968 - C.S. File 54/60-45

Found - 1½" I.P. and brazed cap at corner point and 1894 orig. BTs. (See M34-17 for I.P. reference)

8" now 30" W.Fir, sawed stump, N.65°E., 53.5 ft., open top of stump and find reverse scribe marks.
30" now 48" Fir, shattered stump, S.40°W., 121.4 ft., showed old scar.

8" now 28" W.Fir, snag, N.21°W., 116.4 ft. (Rec. 97.7), previously opened and shows "S9" scribe.

At corner point in place of unrecorded pipe:

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 9 W

CC S 9
S 16

1968

Reset old pipe alongside.

New BTs -7" Alder S.45°W., 57.0 ft. mkd. T22S R9W S16 CC CSBT

13" D.Fir N.84°W., 68.2 ft. mkd. T22S R9W S9 CC CSBT

This cor. lies on gentle E. slope in old logged off area.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1367, surveyed Apr/June 1987 - (DCSO records Vol. 45 Page(s) 18433)

Intersect the W. bdy. of sec. 10, and point for the closing corner of secs. 9 and 16.

Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd: (Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 400503

PRIMARY CORNER DESCRIPTION C.C. for Secs. 9 & 16 (W. bdy. Sec. 10)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

T 22 S
CC $\frac{S 9}{S 16}$ | S 10
R 9 W
1987

from which

A Fir 11" dia., bears S.36°W., 13½ lks. dist., mkd. T22S R9W S16 CC BT.

A Fir 6" dia., bears N.80°W., 33½ lks. dist. mkd. X BT.
Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

From this point, the original closing cor. of secs. 9 and 16, bears N.89°40'00"E., 0.070 chs. dist., perpetuated by person(s) unknown, and further perpetuated and recorded by Tracy in 1968, monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground (alongside of which is an iron post, 1½" dia., firmly set, projecting 2" above ground, with iron cap mkd. S9 S10 S16), with 1968 county brass cap, from which the remains of the original bearing trees:

A sawed Fir stump 28" dia., bears N.66 3/4°E., 81 lks. dist. with healed blaze. (Rec. N.65°E.)

A shattered Fir stump 40" dia., bears S.40°W., 184 lks. dist., no marks visible.

A Fir snag 29" dia., bears N.21°W., 176½ lks. dist. with scribe marks T22S R9W S9 BT visible on decayed blaze. (Rec. 148 lks.)

and bearing trees mkd. by Tracy:

An Alder 11" dia., bears S.45°W., 86½ lks. dist., no marks visible on partially healed blaze.

A Fir 18" dia., bears N.84°W., 103 lks. dist. with healed blaze.

This corner is now amended.