

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. Sec. 4 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1665)

Set Hemlock post, 5 ft. long, 4" sq., 24" in ground, on hillside sloping W. for ¼ sec. corner, mkd. ¼ S. on the W. face, from which
A Fir 36" dia., bears S.42°E., 49 lks. dist. mkd. ¼ S BT
A Fir 36" dia., bears S.72°W., 35 lks. dist. mkd. ¼ S BT

Survey by V.W. Hosford - Aug. 1954 - C.S. File 41/292 and M 10-80

The East 1/4 S 4. At this corner I found a 4" Hemlock post. The original BT for sec. 5 is badly burned and decayed stump. The original BT for sec. 4 is a dead stump with overlay of scribing visible.

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1367, surveyed Apr/June 1987 - (DCSO records Vol. 45 Page(s) 18428-29)

The ¼ sec. cor. of sec. 4 only, perpetuated and recorded by Vernon W. Hosford, in 1954, monumented with an iron pipe 1" dia., firmly set, projecting 2" above ground, from which the remains of an original bearing tree:

A badly decayed Fir stump, size indeterminate, bears S.72°W., 35 lks. dist., with reverse scribe marks ¼ visible on decayed Fir slab.

At the corner point

Set an stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, directly over the iron pipe, with brass cap mkd:

T 22 S R 9 W

¼

S 4

1987

from which

A Fir 9" dia., bears S.25¼°W., 26 lks. dist. mkd. X BT.

A Fir 10" dia., bears N.64½°W., 31½ lks. mkd. ¼ S4 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Corner is located 1 ch. W. of a dirt road, 25 lks. wide, bears N.80°E. and S.15°W.

Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19875-6)