

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which new bearing trees
A Hemlock 25" dia., bears S.32°E., 59 lks. dist. mkd. ¼
S23 BT.
A Hemlock 27" dia., bears N.11°W., 107 lks. dist. mkd. ¼
S22 BT.

Survey by Les Roberts, PLS #1039 - For: International Paper Co. - Sept. 1983 - C.S. File 58/280 and M 90-52

Found - 1983 BLM brass cap. (as yet unapproved)
23" Fir bears S.32°E., 37.7 ft., scribe visible.
1974 BT.
24" Hemlock bears N.10°W., 70.2 ft., scribe visible.
1974 BT.

(See entry prior to this one for the 1983 BLM survey-filed after Roberts survey)

Found OK by R.Quimby, February 1997 - M 124-42

Brent Knapp - For: Roseburg Resouces - 2/24/2025 - M184-62

Found - Brass cap marked "T22S R9W ¼ S22 S23 1983"
Rotten stump N.08°W. 70.8'
34" D. Fir with tag N.63°E. 11.1' with healed blaze
no record.
39" D. Fir with tag S.32°E. 37.7' with healed blaze.
Hemlock stump N.08°W. 70.8' (rec N.12°W. 56lks &
N.10°W. 70.2')
New - 10" D. Fir S.72°W. 22.9' scribed "S.¼ S22 BT"
15" D. Fir N.43°W. 30.1' scribed "S.¼ S22 BT"
OCRS COORDINATE SYSTEM
COTTAGE GROVE-CANYONVILLE ZONE