

PRIMARY CORNER DESCRIPTION Sec. cor. for 10, 11, 14 and 15

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1625)

Set post, a Fir, 5 ft. long, 4½" dia., 18" in ground, for cor. to secs. 10, 11, 14 and 15, from which:
A Fir 30" dia., bears N.45°E., 200 lks. dist.
A Fir 60" dia., bears S.76°E., 39 lks. dist.
A Fir 14" dia., bears S.48½°W., 220 lks. dist.
A W.Oak 12" dia., bears N.41½°W., 230 lks. dist.

Cor. fd. & used March 29, 1895 in GLO survey by Elmer Worrick, under contract #632 - (DCSO records, Vol. 4 Pages 1714-15)

Wilford N. Haines - May 16, 1967 - C.S. File 55/47 and M 34-31

(Corner Report)
Point used for corner, none set, from which
6' or 7' Fir stub, S.76°E., 39 lks., no scribe found.
Burned stub of Fir, N.39°10'E., 2.3 chs., no scribe found.
14" Fir now 4' or 5', looks like BT but did not open. Sets on top edge of bluff or slide, S.59°00'W., 2.3 chs.
3/16" alum. pin with about ½" head, N.62°02'E., 8.02 (?)
I have talked to International Paper Co. Engineers and find that these pins are darning needles and that since the Oxbow fire, they are using steel instead of alum.

Survey by Bruce A. Shaner - For: Reservation Ranch - Aug. 26, 1977 - M 70-32

Set Brass cap mkd. T22S R9W WM 10, 11, 14, 15 1977, from which
60" D.Fir, orig. BT, now 7 ft. dia. burned out hole with stubs and old USGLO location post, bears S.76°E., 25.7 ft.
16" D.Fir, orig. BT, now 52" w/old face, old "X" & scars, bears S.59°W., 151.8 ft. (Rec. S.48½°W. 145.9 ft.)
36" D.Fir, orig. BT, now big stub, bears N.39°E., 151.7 ft. (Rec. N.45°E., 132.0 ft.)
Above evidence noted by Haines in 1967, I concur.
52" D.Fir, orig. BT, I rescribe "T22S R9W S15 BT", bears S.59°W., 151.8 ft.
24" D.Fir, I scribe T22S R9W S10 BT bears N.47°W., 62.5 ft
22" D.Fir, I scribe T22S R9W S10 BT bears N.24°E., 27.0 ft
28" D.Fir, I scribe T22S R9W S14 BT bears S.73°E., 67.2 ft

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. cor. for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19861)

From the cor. of secs. 10, 11, 14 & 15, perpetuated by Haines, in 1967, recorded in the Douglas County Courthouse File No. 55/47 and M 34-31, & further perpetuated by Shaner, in 1977; monumented with an iron post, 2½" diam., firmly set, projecting 5" above ground, with brass cap mkd.

T 22 S R 9 W
 10 11
 15 14
 1977

from which the remains of the original bearing trees

 A fir stub, size indeterminate, bears S.76°E., 39 lks., no marks visible.

 A fir, 65" diam., bears S.59°W., 230 lks., with illegible scribe marks visible on an open face. (Record, S.48½°W., 221 lks.)

and bearing trees mkd. by Shaner

 A fir stump, 31" diam., bears S.75°E., 101 lks., no marks visible on a decayed face.

 A fir, 34" diam., bears N.24°E., 39½ lks., with healed face.

 A fir, 40" diam., bears N.47°W., 94½ lks., with healed blaze.

and a new bearing tree

 A fir, 5" diam., bears S.29½°E., 57½ lks., mkd. X BT.

Found OK by T. Rambo, Oct. 2000 - M136-10