

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1690-91)

-----  
Set Chinquapin Post 4½ ft. long, 4" sq., 24" in the ground, for ¼ sec. corner, mkd. ¼ S on the N. face, from which,  
A Fir 30" dia., bears N.8°E., 20 lks. dist. mkd. ¼ S BT.  
A Fir 24" dia., bears S.2°W., 72 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V Perron, crew - Feb. 28, 1968 - C.S. File 54/60-41

-----  
Found - Orig. 30" now 36" Fir, down, N.8°E., 13.2 ft. previously opened and shows "¼S" scribe and axe notch.

Orig. 24" now 34" Fir stump, S.2°W., 47.5 ft., shows good scar, we do not open.

Set Brass cap at cor. mkd: County Surveyors Office

T 22 S R 9 W

¼ S 26  
S 35  
1968

New BTs -14" Chinquapin S.71°W., 46.7 ft. mkd. ¼ S35 CS BT.  
6" D.Fir N.58°E., 37.8 ft. mkd. ¼ S26 CS BT.

This corner lies on bench sloping SW in dense rhododendron.

Cor. Fd. OK, Jan. 1983, by R. Luckman - M 93-41

Mark Smalley - For: Roseburg Forest Products - Bill Olson - Ralph McManis - Nov 1998 - C.S. File 65/23-1

-----  
Found - 1968 DCSO IPBC  
37" Fir stump, S.2°W., 47.5 ft., Orig.  
24" Chinquapin, S.71°W., 46.7 ft., good - partially healed.

15" Fir, N.58°E., 37.8 ft., good - healed face.

New BTs- 9" Fir, N.48°W., 14.5 ft., scribed "¼ S BT"

11" Fir, S.4°E., 10.1 ft., scribed "¼ S BT"