

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1683-84)

Set Maple post 4½ ft. long, 4" sq., 24" in the ground on hillside sloping West for the corner to secs. 25, 26, 35 and 36, mkd. T22S S25 on the NE.; R9W S36 on the SE.; S35 on the SW.; and S26 on the NW. faces, with 1 notch on the S. and E. edges, from which,

- A Fir 30" dia., N.80°E., 68 lks. mkd. T22S R9W S25 BT.
- A Fir 48" dia., bears S.68°E., 135 lks. dist. mkd. T22S R9W S36 BT.
- A Fir 36" dia., bears S.25°W., 133 lks. dist. mkd. T22S R9W S35 BT.
- A Fir 32" dia., N.27°W., 29 lks. mkd. T22S R9W S26 BT.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - John Powell and Randy Smith, crew - Dec. 14, 1982 - C.S. 62/1-35

Found - Recently set 1½" Iron pipe with brass cap set by Luckman Surveying. (See M 93-41 for note in narrative)

- Orig. 48" Fir now 40" rotting stump. I open and find scribed "T22S R9W S36"
- Orig. 36" Fir now 39" rotting stump. I open and find scribed "T22S R9W S35"

Since found brass cap did not agree with found original BTs, I SET 1" x 30" Iron pipe with brass cap using record bearings and distances from both BTs. Cap mkd: Douglas Co. Surveyor

T	22	S	R	9	W	
		S	26		S	25
		S	35		S	36
						1982

from which,

- Orig. 48" now 40" Fir stump bears S.68°E., 89.1 ft.
- Orig. 36" now 39" Fir stump bears S.25°W., 87.8 ft.
- The found brass cap bears N.79½°W., 34.9 ft. from corner I set.

New BTs -12" Hemlock scribed "T22S R9W S25 CS BT" in double blaze, bears N.72°E., 48.5 ft.

10" Fir scribed "T22S R9W S36 CS BT" in double blaze bears S.61°E., 33.8 ft.

10" Hemlock scribed "T22S R9W S35 CS BT" in double blaze, bears S.16°W., 42.3 ft.

15" Fir scribed "T22S R9W S26 CS BT" in double blaze, bears N.81°W., 18.3 ft.

Douglas Co. BT tags on all trees.

Cont.

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21731-2)

The cor. of secs. 25, 26, 35, and 36, perpetuated by the Douglas County Surveyors Office, in 1982, monumented with an iron post, 1" dia., firmly set, projecting 13" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A burned decayed fir stump, 36" dia., bears S.68°E., 89.1 ft., with scribe marks T22S R9W S36 visible on open blaze.

A decayed fir stump, 39" dia., bears S.25°W., 87.8 ft., with scribe marks S R9W S35 and other illegible scribe marks visible on open blaze.

and the remains of the bearing trees mkd. by the Douglas County Surveyors Office, in 1982

A hemlock stump, 21" dia., bears N.72¼°E., 48.5 ft., with a healed double blaze.

A fir stump, 19" dia., bears S.60¼°E., 33.3 ft., with a healed double blaze.

A hemlock, 19" dia., bears S.16½°W., 41.5 ft., with a healed double blaze.

A roothole bears N.81°W., 18.3 ft., with a down burned fir stump, 23" dia., alongside, with a healed double blaze. and a new bearing tree

A fir, 31" dia., bears N.85¼°E., 79.9 ft., mkd. T22S R9W S25 BT.

No suitable trees available to the SE. or NW.

An aluminum fence post, bent flat, is alongside the cor. Corner is located on the NE. and SW. cors. of timber, edges bear N., S., E., and W., with young fir reproduction to SE. and newly logged area to NW.; and NE., 20 ft. from creek, 2 ft. wide, course S. 25° E.