

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1631)

Set a stone 18 x 10 x 8 for corner to secs. 13, 14, 23 and 24, from which
A Fir 30" dia., bears N.55°E., 32 lks. dist.
A Fir 36" dia., bears S.23°E., 8 lks. dist.
A Fir 20" dia., bears S.43°W., 31 lks. dist.
A Fir 24" dia., bears N.31°W., 68 lks. dist.

Wilford N. Haines - For: August Sagaberd Est. - July 1967 - M 34-31; C.S. File 55/47 and Haines F.B. H-96

Found - Rock with chisel marks. 1" hex steel driven alongside.
Old Fir snag, N.E. 8 lks. (Not S.23°E.)
No other trees that I could make fit for other BTs.
Old blazes to East indicated this point has been used for 50 years or more for the corner. Top of ridge to West and North fits orig. notes.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16034)

The sec. cor., perpetuated and recorded by Haines in 1967, monumented with an iron pin, 1" dia., firmly set, projecting 2" above ground, from which the only remaining original bearing tree:

A Fir 40" dia., bears N.23°E., 8 lks. dist., with scribe marks T22S R9W S BT visible on portion of decayed blaze lying alongside. (Rec. S.23°E.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, directly over iron pin, with brass cap mkd:

T 22 S R 9 W
S 14 | S 13
S 23 | S 24
1973

from which new bearing trees:

A Fir 11" dia., bears N.79°E., 84 lks. dist. mkd. T22S R9W S13 BT.

A Maple 10" dia., bears S.44°E., 35 lks. dist. mkd. T22S R9W S24 BT.

A Fir 10" dia., S.85°W., 64 lks. mkd. T22S R9W S23 BT.

A Fir 10" dia., N.51°W., 50 lks. mkd. T22S R9W S14 BT.

PRIMARY CORNER DESCRIPTION Cor. Secs. 13, 14, 23, & 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, and Richard L. Sanford, Surveying Technician, under Group No. 1704, surveyed July 1993 thru June 1995 (DCSO records Vol. 52 Page(s) 19713

The cor. of secs. 13, 14, 23 and 24, monumented with an iron post, 2½ ins. diam., firmly set, projecting 6 ins. above ground, with properly mkd. brass cap.

from which the remains of bearing trees by Wofford, Rogers and Chatters

A fir, 22 ins. diam., bears N. 77° E., 84 lks. dist., with healed blaze. (Record, N. 79° E.)

A maple stump, 11 ins. diam., bears S. 44° E., 35 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

A fir, 17 ins. diam., bears S. 89° W., 62 lks. dist., with healed blaze. (Record, S. 85° W., 64 lks.)

A fir, 16 ins. diam., bears N. 58° W., 50 lks. dist., with healed blaze. (Record, N. 51° W.)

and a new bearing tree

A fir, 11 ins. diam., bears S. 17½° E., 39½ lks. dist., mkd. T22S R9W S24 BT.

The corner is located on a steep SE. slope.

Ron Rice, NW Land Surveying - Jason Collver - May 2012 - C.S. File 65/76-55

Condition report only

Found - 3¼" BLM brass cap on iron pipe, dated 1973

A fir, 22" dia., bears N.77°E., 84 lks., with healed blaze. (Fd. a 32" dia., Fir with a healed face)

A maple stump, 11" dia., bears S.44°E., 35 lks., with fragmentary scribe marks visible on partially healed blaze. (Fd. in same condition)

A fir, 17" dia., bears S.89°W., 62 lks., with healed blaze. (Fd. a 23" dia., fir with a healed face)

A fir, 16" dia., bears N.58°W., 50 lks., with healed blaze. (Fd. a 17" dia., Fir with a healed face)

A fir, 11" dia., bears S.17½°E., 39½ lks., mkd. T22S R9W S24 BT. (Fd. a 18" dia., Fir with a healed face)

Note - Corner has steel post adjacent to it. All BTs have red painted bands and yellow tags.

Compass decl. 16° East.