

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1633)

Marked a Fir 24" dia., for the ¼ sec. corner. No trees near.

Douglas County Surveyors Office - James W. Byron, Surveyor - C.S. File 54/60-8 - Dec. 1967

Corner searched for, not found. Logged and burned many years ago.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16064)

The ¼ sec. cor. of secs. 24 and 25, perpetuated by person(s) unknown, monumented with a wooden stake, 4 x 4 x 36 ins., firmly set 18" in the ground, in the root hole of the original corner tree, lying alongside, a Fir 40" dia., with scribe marks 1 S visible on open blaze on one side and healed blaze on opposite side.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:

T 22 S R 9 W

¼ S 24
S 25

1979

from which

A Fir 6" dia., bears N.29°W., 12 lks. dist. mkd. ¼ S24 BT

An Alder 7" dia., bears S.57½°E., 5 lks. dist. mkd. ¼ S25 BT.

Reset wooden stake alongside iron post.

Found OK by R. Quimby, February 1997 - M 124-42

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21736-37)

The ¼ sec. cor. of secs. 24 and 25, monumented with an iron post, 2½" dia., firmly set, projecting 1 in. above ground, with brass cap (properly) mkd.

from which the bearing trees mkd. by Wofford, Rogers, and Chatters in 1973-79

continued next page

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

An alder, 10" dia., bears S.57½°E., 3.3 ft., with a decayed face visible in partially healed blaze.
A fir, 17" dia., bears N.29°W., 7.9 ft., with a healed blaze.
Corner is located in the roothole of original corner tree, a down fir, 40" dia., no marks visible, with an aluminum fence post alongside.