

PRIMARY CORNER DESCRIPTION NW Cor. of T23S R8W

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2550)

Set a post 4½ ft. long, 4" sq., 24" in the ground for NW cor. to Tp. 23 S., R8W., marked R8W S6 on E.; T23S on S.; and R9W on W. with 6 notches on S. and E. sides, from which

A Fir 20" dia., bears S.30°E., 45 lks. dist. mkd. T23S R8W S6 BT.

A Fir 40" dia., N.40°W., 41 lks. mkd. T23S R9W S1 BT.

NW Cor. T23S R8W. (Corrected as follows:)

I obliterate marks relating to R9W on post and BT and mark on NW BT, T23S R8W S6 BT.

A Dogwood 5" dia., bears N.12°E., 60 lks. dist. which I mark T23S R8W S6 BT. (June 21st, 1896)

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon "Ray" Tracy, crew - March 1963 - C.S. File 52/14-56

Found - 40" Fir stump, badly burned, N.40°W., 27.1 ft., found scribing, "S6 W" at bottom edge of upper face. BT scar completely burned.

Stump hole with Fir roots, S.30°E., 29.5 ft.

No trace of Dogwood to NE. Area has been logged and burned.

Set Brass cap at cor. mkd: County Surveyors Office

T 23 S S 1		S 36	T22-9W
R 9 W		S 6	T23-8

1963

Rescribe 40" Fir stump N.40°W., 27.1', mkd: T23S R9W S1 CSBT

New BT - 9" D.Fir S.70°E., 56.2 ft. mkd. T23S R8W S6 CS BT.

No other live trees near.

Corner lies on West slope approx. 300 ft. West of ridge top.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, E. West, crew - Feb. 1967 - C.S. File 54/12-65

Found - 1963 Co. surveyor brass cap.

Orig. 40" Fir stump N.40°W., 27.1 ft., rescribed "T23S R8W S6 CS BT"

9" now 12" D.Fir S.70°E., 56.2 ft., alive, scribe visible on nearly healed blaze.

New BTs -4" D.Fir N.49°E., 26.5 ft. mkd. CS BT.

4" D.Fir N.21°W., 115.5 ft. mkd. CS BT.

This corner lies approx. 300 ft. W. of top of spur ridge on moderate West slope. (Cont. Next Page)

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 671100

PRIMARY CORNER DESCRIPTION NW Cor. of T23S R8W

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Harvey E. Wofford and Stephen J. Malloy, Cadastral Surveyors, under Group #1074, surveyed July 1980/Nov. 1982 - (DCSO records Vol. 43 Page(s) 16851-52)

True point for the NW. cor. of T23S R8W.
Set an alum. post, 28" long, 2½" dia., 24" in the ground, with alum. cap mkd:

		T 22 S
		R 9 W
T 23 S		S 36
R 9 W		T 23 S
S 1		R 8 W
		S 6

1980

from which

- A Fir 4" dia., bears S.60¼°E., 58 lks. dist. mkd. X BT.
- A Fir 10" dia., bears S.23½°E., 44 lks. dist. mkd. T23S R8W S6 BT.

From this point, the original NW. cor. of T23S R8W, bears S.89°51'W., 0.14 chs. dist., perpetuated and recorded by Godfrey, in 1963, monumented with an iron post, 1½" dia., firmly set, projecting 7" above ground with 1963 county brass cap, from which the remains of an original bearing tree:

- A Fir stump 47" dia., bears N.40°W., 1 lks. dist., rescribed T23S R9W S1 CS BT by Godfrey.
- and a bearing tree mkd. by Godfrey:
 - A Fir 18" dia., bears S.71°E., 85 lks. dist., with healed blaze.
- and a bearing tree mkd. by Vernon Tracy in 1966:
 - A Fir 15" dia., bears N.49°E., 40 lks. dist., with healed blaze.