

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 700540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 12; & S. 7, T22-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 202 survey dated March 11, 1874 (DCSO records Vol. 4 Page(s) 1588)

Marked a Fir 12" dia. for ¼ sec. cor., from which
A Fir 10" dia., bears S.30°E., 11 lks. dist.
A Fir 12" dia., bears N.50°W., 20 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Wm. Stoffel, crew - Sept. 1963 - C.S. File 52/14-74

Found - Dead Fir snag 22" dia. & approx. 35 ft. high.
Dead Fir snag, 18" dia. & approx. 20 ft. high,
N.50°W., 13.2 ft., opened and found good scribing
"BT"

Rotten piece of Fir stump S.30°E., 7.2 ft., too far gone to find any markings.

Set Witness Corner 6 ft. N. of ¼ corner.

Set brass cap for cor. mkd: County Surveyors Office
T 22 S
R9W W.C. ¼ S12 | S 7 R8W
6 ft. S. to Corner
1963

New BTs -27" Fir stump N.40°W., 19.0 ft. mkd. W C ¼ S12 CSBT
27" Fir snag S.84°E., 31.6 ft. mkd. W C ¼ S7 CS BT.
No live trees available.

Fd. OK, August 1991, H. Wilcox, M 113-60

Victor McLind - for: Menasha Corp. - Dec. 1996 - M 126-23

Found- Rotted remains of Cor. tree
Co. Surveyors's witness cor., a 1½" I.P. with 2½"
BR. Cap, mkd. "T22S WC R9W ¼ S12 S7 S8 corner is
6' south 1963".

BT's Fd.- 25" rotted Fir stump, scribes "WC ¼ S12 CSBT",
N.39°W., 18.2'.
17" rotted Stump, scribed "WC ¼ S7 CSBT", on
windfall, S.85°E., 31'.

9" Fir, scribes visible, S.11°W., 9.6'.

8" Fir, scribes visible, S.87°W., 6.9'.

New Bt's- 11" Fir, scribed "WC ¼ S7 BT", S.27°E., 14'.

8" Fir, scribed "WC ¼ S7 BT", N.83°E., 28.5'

Note: All bearings and distances are from the witness corner. True corner was calculated at south 6' from W.C.

continued next page

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 700540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 12; & S. 7, T22-8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM remonumentation by Aaron M Graham, Cadastral Surveyor and Michael Jones Surveying Technician under Group #2199 surveyed April 2008/April 2009 - (DCSO rec Vol 56 Pgs 21936-7)

The ¼ sec. cor. of secs. 7 & 12, monumented with the remains of the original corner tree, a decayed fir stump, size indeterminate, no marks visible, perpetuated by Godfrey in 1962-63, subsequently perpetuated by Wilcox in 1991, and further perpetuated by McLind in 1996, from which the remains of an original bearing tree

A decayed fir stump, size indeterminate, bears N.50°W., 13.2 ft., no marks visible.

No other suitable bearing objects available due to recent logging actives.

At the corner point

Drive a steel reinforcing bar, 36" long, 5/8" dia., 36" in the stump, with alum. cap mkd.

T 22 S
R 9 W R 8 W
1/4
S 12 | S 7
2008

From this cor., a point established by Godfrey in 1962-63, as a witness corner for the ¼ sec. cor. of secs. 7 and 12, bears North, 6.0 ft., monumented with an iron post, 1½" dia., firmly set, projecting 9" above ground, with a brass cap mkd. COUNTY SURVEYORS OFFICE T22S R9W R8W WC ¼ S12 S7 COR IS 6' SOUTH 1963.

from which the remains of a BT mkd. by Godfrey in 1962-63

A fir stump, size indeterminate, bears N.40°W., 19.0 ft., with scribe marks WC ¼ S12 CS BT visible.

and the bearing trees mkd by Wilcox in 1991

A fir, 11" dia. bears S.11°W., 9.6 ft. with a healed blaze

A fir, 11" dia. bears S.87°W., 6.9 ft. with a healed blaze

and the bearing trees mkd. by McLind in 1996

A fir, 10" dia. bears N.83°E. 28.5 ft. with a healed blaze

A fir, 13" dia. bears S.27°E., 14.0 ft with a healed blaze