

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. Cor.)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1764-65)

I set a sandstone 20x12x8 ins., 15" in the ground for C.C. to T22S Rs. 10 and 11 W. marked with C C and 6 notches on E. and W. edges, from which,
A Fir 36" dia., bears N.73°E., 44 lks. dist. mkd. T22S CC R10 and 11 W S31 BT.
A Fir 30" dia., bears S.24°W., 12 lks. dist. mkd. T22S CC R10 & 11 W S1 BT.
A Fir 40" dia., bears N.55°W., 29 lks. dist. mkd. T22S CC R10 & 11 W S6 BT.

Sandstone found and used in GLO resurvey by A. Gould, under Contract #762 dated July 1905 (DCSO records, Vol. 5 Page 1976)

Survey by Arnold Gibson - For: Oregon State Board of Forestry Charles Cook, Engineer - Nov. 22, 1971 - C.S. File 55/265-1; M 45-3 and C.S. File 55/233-6

Original 20" x 12" x 8" stone, in place, no marks visible, from which a:
36" Fir bears N.73°E., 44 lks., now 50" rotten snag 30 ft. tall, in place, no marks visible.
30" Fir bears S.24°W., 12 lks., now 28" rotten stub in place, scribes S31 B visible.
40" Fir bears N.55°W., 29 lks., now missing.
Set 1½" x 36" galv. I.pipe with 3" bronze cap marked "Oregon State Board of Forestry T22S R10W S31 T23S R11W S1 1971 RS 359", 35" in ground with original stone alongside, and from which a:
22" Fir bears N.42°E., 10.6 ft. to face; scribed T22S R10W S31 BT 359.
33" Fir bears N.09°W., 10.6 ft. to face, scribed T22S R10W S31 BT.
Set 4" x 4" x 72" white painted cedar post 2.7 ft., S.01°W. of corner pipe. OSBFD metal location poster on 33" Fir BT.

James M. McIntosh, Oregon Dept. of Forestry - Witness: Ralph C. Hall - 6/2011 - C.S. File 65/72-30

Found - Orig by Todd, 1894: 20x12x8" stone (in place, no marks visible) from which a:
36" Fir N.73°E. 44 lks.; now 44" x 3 ft. high rotted stump in place, face rotted.

continued next page

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (SW Tsp. Cor.)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

30" Fir S.24°W. 12 lks.; now 12" x 2 ft. high rotted stub in place, no marks visible.
40" Fir N.55°W., 29 lks.; missing.
Restoration by Arnold G. Gibson, 1971 OSBF 1½"x36" galv. iron pipe with 3" bronze cap from which a:
22" Fir N.42°E., 10.60 ft.; now 23" in place, face closed, added bearing tree tag.
33" Fir N.09°W., 10.60 ft.; now 42" N09°E, face closed, with yellow metal location poster.
4"x4"x72" White Painted Cedar Post S.01°W., 2.7 ft. missing.
REWITNESSED from the above pipe and cap:
Carsonite witness post N.71°W., 2.60 ft. to base.
Carsonite witness post S.20°E., 2.10 ft. to base.
Magnetic variation set at 19° East.