

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31, T21-10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 - (DCSO records Vol. 3 Page(s) 1192-93)

-----  
I set a sandstone in the ground, for closing cor. to townships 21 S., Ranges 10 and 11 W., (8.25 chs. E. of cor. to Tp. 22 S., R.10 & 11 W.) marked C C with 6 notches on N, E, and W. edges, and raised a mound of stone 1½ ft. high, 2 ft. base, alongside, pits impracticable.

Corner searched for not found, by Frank D. Maxwell, Forest Service Surveyor, 1914 (DCSO records Vol 28 Pages 11994 and 11995.) On page 11995, notation by Maxwell states:

"Fall 112 lks. S.1°28'E. of Cor. No. 1 of listing survey, identical with what has been considered by settlers in the vicinity as the closing cor. of T21S Rs. 10 and 11 W., which is a post, 3" sq., set in a mound of stone, witnessed by two bearing trees. Old settlers inform me that about 20 years ago W.H. Byars, in a private survey, set this post and marked it for closing cor. of T21S., Rs. 10 and 11 W. The bearing trees were added by the listing surveyor. I do not consider this the original closing township cor., but leave it as found.

In a examination of Maxwell corners ordered by the Surveyor General in Sept. 1915, executed by Frederick W. Rase, Surveyor, Forest Service (DCSO Records, Vol. 28 Page 1197: Rase states:

"I make diligent search for traces of the closing cor. of T21S Rs. 10 and 11 W., but find none. I examine the post reported by Surveyor Maxwell as being identical with Cor. No. 1 of listing survey, considered for many years by the settlers to be the closing cor. of T21S., Rs. 10 and 11W. This, besides being a post, instead of a stone as reported, is about 12 chs. farther East than supposed to have been originally set. I do not consider this to be the true corner."

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1050)

-----  
(Cont. Next Page)

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 109700

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31, T21-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Apportioned Distance.  
Set an Iron post, 3 ft. long, 3" dia., 24" in the ground, for closing cor. of Tps. 21 S., Rs. 10 and 11 W., with brass cap marked:

CC  
T21S  
R11W R10W  
S36 S31  
1919

from which

A Fir 12" dia., bears N.66°E., 25 lks. dist. mkd. C C T21S  
R10W S31 BT.

A Fir 10" dia., bears N.70°W., 7 lks. dist. mkd. C C T21S  
R11W S36 BT.

Fd. cor. Jan. 1958 by G.R. Lecklider - M 8-29

Survey by James W. Prochnau PLS #1305 - For: U.S. Forest Service - July 1985 - M 99-21 A&B

-----  
Found - 3½" brass cap on 2½" iron pipe set by GLO. 1919  
20" D.Fir bears N.66°W., 4.2 ft. (Rec. N.70°W., 4.6 ft.) healed.  
Unrecorded BT, 11" D.Fir bears N.86°E., 5.8 ft., healed.