

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec. cor. for 31 and 32 only (South)

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 4 Page(s) 1744)

Set a Fir post 5 ft. long, 5" dia., 20" in ground for the cor. to secs. 31 and 32, from which
A Fir 10" dia., bears N.63°E., 67 lks. dist.
A Fir 10" dia., bears N.65°W., 48 lks. dist.

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1762-63)

Timber burned and all traces of lines and corners destroyed. Set a Post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 31 and 32 mkd. S32 on E.; T22S R10W on N.; S31 on W., with 1 notch on W. and 5 notches on E. faces, from which
A Fir 20" dia., bears N.42°E., 8 lks. dist. mkd. T22S R10W S32 BT.
A Fir 12" dia., bears S.4°E., 18 lks. dist. mkd. T22S R10W S31 & 32 BT.
A Fir 16" dia., bears N.40°W., 30 lks. dist. mkd. T22S R10W S31 BT.

GLO survey by Levi C. Walker, Deputy Surveyor, under Contract #763, dated June 20, 1905 - (DCSO records Vol. 5 Page(s) 1846)

Intersect the cor. to secs. 31 and 32, T22S R10W, which is a post, firmly set, marked and witnessed as described by the Surveyor General.