

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 203600

PRIMARY CORNER DESCRIPTION M.C. South Bdy. Section 5

Alias <u>881380</u>	Description <u>M.C. Right bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1730)

Marked a Double Alder each 5" dia. for M. post bet. secs. 5 and 8.

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 5 Page(s) 1843)

A Willow 5" dia., which I marked T22S R10W MC on W.; S5 on N.; S8 on S. sides for meander cor. bet. secs. 5 and 8, from which

An Alder 8" dia., bears S.80°W., 15 lks. dist. mkd. T22S R10W S8 MC BT.

A Spruce 20" dia., bears N.35°W., 100 lks. dist. mkd. T22S R10W S6 BT MC.

A Fir 30" dia., bears N.1°E., 30 lks. dist. mkd. T22S R10W S5 MC BT.

An Alder 4" dia., bears S.79°E., 20 lks. dist. mkd. T22S R10W S8 MC BT.

Survey by G. Robert Lecklider - For: General Construction Co. June 1960 - M 19-14

Found - 56" Fir, N.1°E., 19.8ft., chopped open.

Spruce stump hole, N.35°W., 66 ft.

Set 3/4" x 54" Pipe.

20" Fir, S.20°E., 86.0 ft.