

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 32 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 4 Page(s) 1744)

Set a Fir post, 5 ft. long, 5" dia., 20" in ground for the ¼ sec. cor. on S. bdy. of sec. 32, from which
A Fir 10" dia., bears N.40°E., 38 lks. dist.
A Fir 10" dia., bears S.9°W., 64 lks. dist.

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1762)

(37.50 chs.)
A Post 5" dia., firmly set 2 ft. above ground for ¼ sec. cor. mkd. ¼ S. on N. face, from which
A Fir 10" dia., bears N.40°E., 38 lks. dist. mkd. ¼ S BT.
A Fir 10" dia., bears S.9°W., 64 lks. dist. mkd. ¼ S BT.
I destroy this cor. and at:
(40.00 chs. West)
Set a post 4" sq., 5 ft. long, 24" in the ground for ¼ sec. cor. mkd. ¼ S. on N. fce, from which
A Fir 12" dia., bears S.60°E., 32 lks. dist. mkd. ¼ S BT.
A Fir 12" dia., bears S.33°W., 15 lks. dist. mkd. ¼ S BT.

GLO survey by Levi C.Walker, Deputy Surveyor, under Contract #763, dated June 20, 1905 - (DCSO records Vol. 5 Page 1846 A)

The 1/4 Sec. cor., which is a Fir post, 4" sq., 24" above ground, firmly set and marked ¼ S on N. face; from which
A Fir 18" dia., bears N.52°W., 20 lks. dist. mkd. ¼ S BT.
A Fir 18" dia., bears S.60°W., 37 lks. dist. mkd. ¼ S BT.
These marks had about 12 years growth over them. After diligent search, I find no trace of cor. as set under Contract #292.