

PRIMARY CORNER DESCRIPTION NW Sec. cor. for Sec. 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 5 Page(s) 1825)

At this point (East of cor. to 8 & 9), I set a sandstone 20x16x12 ins., 16" in the ground for closing cor. to secs. 16 & 17 marked C C with 4 notches on E. and S. edges, from which
A Fir 28" dia., bears N.10°E., 152 lks. dist. mkd. T22S R10W CC S16 & 17 BT.
A Fir 10" dia., bears S.37°E., 57 lks. dist. mkd. T22S R10W S16 BT.
A Fir 36" dia., bears N.1°W., 150 lks. dist. mkd. T22S R10W CC S16 & 17 BT.
Erected a mound of stone 2 ft. high, 4 ft. base around this cor.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Dec. 1971 - C.S. File 55/233-2

Orig. 20"x16"x12" sandstone, missing, from which a:
28" Fir bears N.10°E., 152 lks.; missing, in old burn and slide.
10" Fir bears S.37°E., 57 lks.; now 40" in place, exposed BT.
Set 1½" x 36" I.P. with 3" bronze cap mkd: "Ore St. Bd. of Forestry S17 S8 T22S R10W S16 1971 RS 359", 34" in ground, in mound of rock, and from which a:
29" Fir bears N.66½°E., 34.2 ft. to face, scribed T22S R10W S16 BT.
40" Fir, original, bears S.37°E., 37.6 ft. scribed RS 359
Set 4"x4"x72" white painted cedar post 3.6 ft. S.6°E. of corner pipe.
OSBF metal location poster on 40" Fir BT.

Fd. OK, Sept. 1989 by R. Stuntzner - M 108-75