

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 328700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1044-45)

Set an Iron post 3 ft. long, 1" dia., 26" in the ground, for
¼ sec. cor. of sec. 33 only, with brass cap mkd: ¼ S 33
1919

from which

A Fir 5" dia., bears N.23°E., 28 lks. dist. mkd. ¼ S33 BT.
A Fir 8" dia., bears N.76°W., 23 lks. dist. mkd. ¼ S33 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - June/July 1968 - C.S. 54/1-17

Found - Concrete filled I.P. at corner point, broken off and
brass cap on ground alongside. (Deposit alongside
CS Brass)

Orig. 5" now 10" Fir, alive, N.23°E., 18.5 ft., good
scar. We rescribe above old scar, "¼ S33 CS BT"

Orig. 8" now 14" Fir, alive, N.76°W., 15.2 ft., good
scar. We rescribe above old scar "¼ S33 CS BT"

Set Brass cap at cor. mkd: County Surveyors Office

T 21 S R10W ¼ S 33
T 22 S 1968

This cor. lies 25 ft. West of rock spur, sloping S.40°W., on
steep W. slope.