

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 33 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 4 Page(s) 1743)

Set a Willow post, 4 ft. long, 4" dia., 20" in ground for the 1/4 sec. cor. on S. bdy. of Sec. 33, from which,
A Fir, burned, 48" dia., bears S.11°E., 84 lks. dist.
A Fir, burned, 48" dia., bears N.62°W., 45 lks. dist.

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1760)

(36.00 chs.)
The established 1/4 sec. cor. for the S. bdy. of sec. 33 I was unable to find, it having been destroyed by fire.
(40.00 chs.) (West)
Set a Post 4 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S. on N. face, from which
A Fir 48" dia., bears S.28°W., 75 lks. dist. mkd. 1/4 S BT.
An Alder 4" dia., bears N.88°E., 30 lks. dist. mkd. 1/4 S BT

GLO survey by Levi C.Walker, Deputy Surveyor, under Contract #763, dated June 20, 1905 - (DCSO records Vol. 5 Page 1846 B)

I find no post: only one of the original bearing trees remains; a dead Fir 48" dia., bears S.28°W., 75 lks. dist., by reference to which, I relocate the original cor. point, where I
set a new Fir post, 3 ft. long, 4" sq., 24" in the ground, for 1/4 sec. on S. bdy. of sec. 33; from which
An Alder 8" dia., bears N.8°E., 25 lks. dist. mkd. 1/4 S33 BT (New BT)
A Fir 4" dia., bears S.72°W., 14 lks. dist. mkd. 1/4 S BT. (New BT)
A dead Fir 48" dia., bears S.28°W., 75 lks. dist. mkd. 1/4 S BT. (Original BT)