

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION C C for Secs. 22 and 23 (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1790)

-----  
At a point 930 lks. N.89°51'W. of cor. to secs. 26 and 27, Set a sandstone 20x16x12 ins., 16" in the ground for cor. to secs. 22 and 23, marked C.C. with 2 notches on E. and 2 notches on S. edges, from which

A Maple 12" dia., bears N.54°E., 107 lks. dist. mkd. T22S R10W S23 BT.

A Vine Maple 4" dia., bears S.15°W., 22 lks. dist. mkd. T22S R10W S22 and 23 BT CC.

A Maple 36" dia., bears N.32°W., 72 lks. dist. mkd. T22S R10W S22 BT.

Survey by A.G. Terry and R. Coughlin - For: Al. Peirce Co. - Surveyed Feb. 1955/April 1956 - Filed June 25, 1959 - M 15-17

-----  
4" Post and BTs: 46" Fir N.15°W., 88.0 ft.  
26" Maple N.62½°E., 145.9 ft.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - March 30, 1966 - C.S. File 51/349-1

-----  
Original stone 20"x16"x12", found 4 notches on N., 2 notches on E. and CC on NE faces, from which a:

36" Maple bears N.32°W., 72 lks.; now rotted uproot, sprouts growing out of trunk.

12" Maple bears N.54°E., 107 lks.; remains of rotted stump alongside of five ft. dia. clump, orig. tree lost downstream.

4" Vine Maple bears S.15°W., 22 lks.; missing, sprouts in area.

Trail bears North, 50 lks., in place. Mill Creek bears North 1.50 chs., in place. Mill Creek bears East, 4.30 chs., in place. Beginning of ascent bears West, 70 lks., in place.

Set 4" x 4" x 72" white painted Cedar post, 2.0 ft. South of corner stone in mound of rock, and from which a:

36" Hemlock bears N.20½°W., 61.9 ft.; scribed T22S R10W CC S22 BT RS359.

9' x 8' x 4' high boulder bears N.80°W., 25.7 ft.; scribed X B0.

24" Maple bears N.73½°E., 51.9 ft.; scribed T22S R10W S23 CC BT by Terry in 1956.

Set 4"x4"x72" white painted cedar post for true cor., bears S.02°00'07"E., 58.5 ft.

(Cont. Next Page)

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION C C for Secs. 22 and 23 (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - James Byron, Co. Surveyor -  
July 20, 1966 - C.S. File 54/1-24

-----  
Found - Corner stone at corner, as recorded and orig. NW BT,  
now face down, no scribing found.  
4" x 4" Post as set by Gibson.  
No trace of orig. NE BT. May have been washed out  
by Mill Creek.  
All BTS as recorded by Gibson, 1966. All OK, Rock  
B.O. OK.

Set Brass cap alongside corner stone mkd:  
County Surveyors Office  
T 22 S R 10 W  
CC S 22 | S 23  
S 27  
1966  
Call North to Mill Creek checks OK.