

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION C C for Secs. 14 and 15 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 5 Page(s) 1823)

At point of intersection 3 chs. West of cor. to secs. 11 & 12, I mark a stone in place 24x24x8 ins., above ground with cross (X) at exact cor. point with CC and 2 notches on E. and 4 notches on S. for cor. to secs. 14 and 15, from which

A Fir 48" dia., bears S.1°E., 135 lks. dist. mkd. T22S R10W S14 BT.

A Fir 48" dia., bears S.89°W., 36 lks. dist. mkd. T22S R10W S15 BT.

A Fir 24" dia., bears N.3°W., 55 lks. dist. mkd. T22S R10W CC S14 & 15 BT.

Survey by Harvey Wilcox - For: Jerry Harris - Aug. 1991 - M 113-76 A&B

Found - Stone as called for in original GLO notes, marks plain.

Rotted Fir snag bears S.1°E., 79.7 ft. (89.1 ft. orig.)

Rotted Fir stump bears N.3°W., 36.3 ft. (Orig.)
The orig. SW BT is down.

New BTs -6" Fir bears S.38°W., 17.3 ft. scribed "S15 BT" with X and tag.

6" Fir bears S.34°E., 4.6 ft. scribed "S14 BT" with X and tag.