

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1724)

- 
- A Maple 6" dia., for cor. from which,
  - A Fir 30" dia., bears N.12½°E., 54 lks. dist.
  - A Maple 9" dia., bears S.45°E., 2 lks. dist.
  - A Fir 60" dia., bears S.18°W., 11 lks. dist.
  - A Cherry 5" dia., bears N.60°W., 48 lks. dist.

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 5 Page(s) 1822)

- 
- The cor. to secs. 13, 14, 23 and 24, which I find a Maple 6" dia., mkd. T22S S13 on NE.; R10W S24 on SE.; S23 on SW.; S14 on NW. sides with 1 notch on E. and 3 notches on S. edges, from which
- A Fir 30" dia., bears N.12½°E., 54 lks. dist. mkd. T22S R10W S13 BT.
  - A Maple 10" dia., bears S.45°E., 2 lks. dist. mkd. T22S R10W S24 BT.
  - A Fir 60" dia., bears S.18°W., 11 lks. dist. mkd. T22S R10W S23 BT.
- The Cherry in the notes being gone, I mark
- A Fir 60" dia., bears N.30°W., 35 lks. dist. mkd. T22S R10W S14 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, D. McFarland and J. Powell - For: Doug. Co. Parks Dept. - Sept/Oct 1961 - C.S. File 52/86 and M 22-16

- 
- Found - 1¼" I.P. at corner and Fir snag, burned out face, S.18°W., 7.3 ft. (Unrecorded)  
Now 48" Fir stump that checks for NE. BT.  
No other BTs found.
- New BTs -25" R.Fir bears N.75°E., 24.0 ft. scribed S13 T22S R10W CS BT.  
12" R.Fir bears S.47°E., 35.2 ft. scribed T22S R10W S24 CS BT.  
8" R.Fir bears N.27°W., 37.9 ft. scribed S14 CS BT.  
7" R.Fir bears S.44°W., 44.7 ft. scribed S23 CS BT.

- Fd. OK, July 1981 - M 88-68  
Fd. OK, Sept. 1982 - M 92-81  
Fd. OK, Aug. 1991, by H. Wilcox - M 113-76 B  
FD. 7/2006 - C.S. File 65/59-2 N. Boe

