

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 25; and 30 of T22-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 274 survey dated Sept. 10, 1877 - (DCSO records Vol. 4 Page(s) 1647)

-----  
Marked a Fir tree 8" dia., for the ¼ sec. corner, from which  
An Alder 10" dia., bears S.70°E., 11 lks. dist.  
A Fir 16" dia., bears S.50°W., 21 lks. dist.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1718)

-----  
(Corner report)  
The ¼ sec. cor., which is a Fir 12" dia., marks grown over, from which  
An Alder 14" dia., bears S.70°E., 10 lks. dist. mkd. ¼ S BT.  
A Fir 18" dia., bears S.50°W., 22 lks. dist. mkd. ¼ S BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #718, surveyed April/June 1982 - (DCSO records Vol. 36 Page(s) 14842)

-----  
Point for the ¼ sec. cor. of secs. 25 and 30, determined by the method of irregular boundaries: there is no remaining evidence of the original corner.

Set an Iron post 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

1/4  
S 25 S 30  
R 10 W R 9 W  
T 22 S  
1970

from which

A Fir 14" dia., bears N.71°E., 22½ lks. dist. mkd. ¼ S30 BT.

A Fir 12" dia., bears s.71°W., 15½ lks. dist. mkd. ¼ S25 BT.

Set an iron pipe 36" long, 3/4" dia., 24" in ground alongside the iron post.