

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1 (NE Tsp. Corner)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1748-49)

-----  
Set a post 4 ft. long, 5" sq., 24" in the ground marked T21S S321 on NE.; R9W S6 on SE.; T22S S1 on SW.; R10W S36 on NW. faces, with 6 notches on each edge for cor. to Tps. 21 and 22 S., Rs. 9 and 10 W., from which,  
A Fir 12" dia., N.75°E., 46 lks. mkd. T21S R9W S31 BT.  
A Fir 18" dia., S.62°E., 32 lks. mkd. T22S R9W S6 BT.  
An Alder 4" dia., bears S.72°W., 44 lks. dist. mkd. T22S R10W S1 BT.  
An Alder 5" dia., bears N.38°W., 70 lks. dist. mkd. T21S R10W S36 BT.

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 902)

-----  
Cor. to Tp. 22S R10W, which is an Alder post 3 ft. above ground, 4" sq., mkd. T21S R9W S30 on the NE.; T22S R9W S6 on the SE.; T22S R10W S31 on the SW.; and T22S R10W S36 on the NW. faces, (post not notched), from which,  
A Fir 12" dia., bears N.85°E., 46 lks. dist. mkd. T21S R9W S31 BT.  
A Fir 20" dia., bears S.62°E., 34 lks. dist. mkd. T22S R9W S6 BT.  
An Alder 4" dia., bears S.72°W., 44 lks. dist. mkd. T22S R10W S1 BT.  
An Alder 5" dia., bears N.38°W., 65 lks. dist. mkd. T21S R10W S36 BT.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1037)

-----  
Intersect the old NE cor. of T22S R10W., which is a badly decayed post, marked and witnessed as described by the Surveyor General. Alongside the old post, SET a hard sandstone, 14x12x6 ins., 10" in the ground for NE cor. of T22S R10W., marked with 6 notches on S. and W. edges, from which,  
An Alder 12" dia., bears S.78°W., 43 lks. dist. mkd. T22S R10W S1 BT. (Old BT)

(Cont. Next Page)

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 700700

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1 (NE Tsp. corner)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16028-29)

-----  
The NE. cor. of T22S R10W, monumented with a sandstone, 14 x 12 x 6 ins., firmly set, projecting 8" above ground, mkd. with 6 notches on S. and W. edges, alongside of which is a steel fence post, firmly set, projecting 3 ft. above ground. At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 21 S R 10 W  
-----  
T 22 S | S 36  
R 10 W |  
S 1 |  
1974

from which

A Fir 28" dia., bears S.40°E., 30 lks. dist. mkd. X BT.

A Fir 37" dia., bears N.77°W., 93 lks. dist. mkd. X BT.

No other suitable trees available within limits.

Deposit corner stone and reset steel fence post alongside iron post.

Tony Hostetter - For: Roseburg Resources - Jan. 2020 - C.S.  
File 65/105-10

-----  
Found - 1974 BLM brass cap from which:  
44" Fir, 1974 BT, bears; N.77°W., 61.4 ft to center.