

PRIMARY CORNER DESCRIPTION A.P. on W. bdy. Sec. 18

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1872)

Set a stone 16x12x8 ins., 10" in the ground for cor. to secs. 13 and 24, marked with 3 notches in the N. and S. edges, from which

- A Cherry 16" dia., bears S.57°W., 51 lks. dist. mkd. T22S R12W S24 BT.
- A Spruce 8" dia., bears N.4°W., 25 lks. dist. mkd. T22S R12W S13 BT.
- An Alder 20" dia., bears S.47°E., 16 lks. dist. mkd. T22S R12W S13 & 24 BT.

GLO survey by Charles A. Slang, Deputy Surveyor under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 1978 (duplicate of Pg. 2105) and Page 1980 (duplicate of Pg. 2107)

(Page 1978)

The old cor. of secs. 13 and 24, on the E. bdy. of the Tp., which is nearly destroyed, the stone missing but bearing trees in position.

(Page 1980)

Intersect the old cor. of secs. 13 and 24, already described, 1000 ft. below ¼ sec. cor.

Note: On account of errors in the old work, I cannot close on this cor. so I reestablish it for Angle Point as follows:

Set a sandstone 15x10x8 ins., 10" in the ground for angle cor. marked A P on NE. face, from which

- A Cherry 16" dia., bears S.57°W., 51 lks. dist. mkd. AP BT
- A Spruce 8" dia., bears N.4°W., 25 lks. dist. mkd. AP BT.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - June 23, 1971 - M 44-33

AP corner, reestablished (Orig. cor 13 & 24 by Whipple)

Set OSBF I.P. with 3" bronze cap 34" in ground, from which
9" Alder S.89 3/4°W., 14.2 ft., w/yellow metal location poster)

11" Cedar S.29½°W., 50.8 ft. (RS 359)

White painted cedar post N.W., 1.5 ft.