

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 5 Page(s) 1867)

Set Chittimwood post, 4 ft. long, 4" dia. 20" in ground for 1/4 sec. cor. bet. secs. 7 and 18, from which
 An Alder 12" dia., bears S.55°E., 12 lks. dist.
 An Alder 10" dia., bears N.85°W., 50 lks. dist.
Post stands on top of ridge, course NW. and SE.

Survey by S.O. and H.J. Newhouse - For: Cape Arago Lumber Co. March 1957 - C.S. File 42/256 and M 1-54

We identify corner from original BTs:
 12" Alder S.55°E., 7.9 ft., down and rotted.
 10" Alder N.85°W., 33.0 ft., down.
We also find a Myrtle post, not original, at the correct location of corner.
Set Stone, Iron pipe and post, from which
 24" Fir S.5°E., 25.3 ft. mkd. 1/4 S18 BT.
 16" Cherry N.31°E., 45.0 ft. mkd. 1/4 S7 BT.

Survey by Robert W. Ward Jr. - For: Champion International Corp. - Feb. 24, 1977 (added to record 11/20/2018) - C.S. File 58/139 and M 65-4

Found - A brass cap, iron pipe set by Dennis A. Crowe (P.L.S.845 - could find no record of) The brass cap, iron pipe is at the correct location
 A 24" Fir (now blow down) bears S.5°00'E., 25.3'
 A 16" Cherry (now a snag) bears N.31°00'E., 45.0'
 A 11" ~~Alder~~ Myrtle Wood S.25°00'E., 20.0' (this bearing tree was established by Crowe)

Brent Bacon - For: Menasha Forest Products - 2/2005 - M147-32

Found - 1/2" iron pipe with 2 1/2" brass cap mkd "T22S R11W 1/4 S7 S18 LS845
 9" rotten cherry remains, N.34°E., 44.4' to 'visible scribe "1/4" (record N.31°E.)
 10" myrtle, S25°E., 20.1', healed face
 Uprooted fir, S.3°E., 25.3' (record S.5°E.)
 10" alder, N.4°W., 14.1', visible bark scribe "1/4 T22 R11W S7"

continued next page

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 140500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 7 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Jerry Estabrook - Crew: Pat Coy & John Rondeau - 10/2018 -
C.S. File 65/102-20

Found - A 1/2" iron pipe per M1-54 with 2 1/2" brass cap mkd
"T22S R11W 1/4 S7 S18 LS 845", unknown record.
A 17" Myrtle with visible bark scribe and tag bears
S.25°E., 20.0'
A 24" Fir wind fall bears S.05'E 25.3'.
A rotten alder stump bears N.04°W., 14.1'.
New - A 30" Hemlock, face scribed "N 1/4 S18 BT with X-chop
and tag bears S.63°W., 12.5' to a spike at side
center.

Note - Compass decl. 18°E.
Locations & Comments LAT. AND LONG.
PER GARMIN ETREX HAND HELD GPS
N: 43°39'45.9"

W: 124°03'33.5"