

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. cor. for 17, 18, 19 and 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 5 Page(s) 1866)

Marked a Fir 5" dia. for the cor. to secs. 17, 18, 19 and 20, from which

- A Fir 10" dia., bears N.50°E., 25 lks. dist.
- A Fir 6" dia., bears S.45°E., 22 lks. dist.
- A Hemlock 10" dia., bears S.50°W., 19 lks. dist.
- A Fir 10" dia., bears N.35°W., 40 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1961)

At the old cor. to secs.17, 18, 19 and 20, where I found stumps of original BTs, the cor. tree being gone. I reestablish the cor. as follows viz.

Set an iron rod 4 ft. long and 1/2" dia., 2 ft. in the ground marked with 3 notches on S. and 4 notches on E. sides, from which

- A burnt Fir 36" dia., bears N.1°E., 134 lks. dist. which I mark T22S R11W S17 BT.
- A Cedar 8" dia., bears S.38°E., 94 lks. dist. which I mark T22S R11W S20 BT.
- A Cedar stub 30" dia., bears S.46°W., 66 lks. dist. which I mark T22S R11W S19 BT.
- A burnt Cedar 30" dia., bears N.41°W., 210 lks. dist. which I mark T22S R11W S18 BT.

Elliott State Forest Boundary Survey - L. Beyers and E. Lough Date ? 1941 - (DCSO Field Book 123 Page 8)

From the old bearing trees I set a Hemlock post 4"x4"x4 ft. for cor. to secs. 17, 18, 19 and 20 from which

- A burnt Fir 36" in dia., bears N.1°E., 88 ft.
- A Cedar stub 3 ft. dia., bears S.46°W., 45 ft.
- A burnt Cedar 30" dia., bears N.40°W., 140 ft.
- (ESF BT, An Alder 18" dia., bears S.64°W., 46 ft.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - witnessed by Elbert Driver; Schulson and Hollingsworth - May 24, 1960 - C.S. File 42/403-7

Original 5" Fir, missing; point falls in old landing, from which a

- 10" Fir bears N.50°E., 25 lks.; missing, rotted stub at 35 lks. (Cont. Next Page)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

6" Fir bears S.45°W., 22 lks.; missing, point falls in old landing.
10" Hemlock bears S.50°E., 19 lks.; missing.
10" Fir bears N.35°W., 40 lks.; missing, landing area.
Retracement by Whipple, 1893:
1/2" x 4 ft. I.R.; missing, from which
36" burnt Fir bears N.1°E., 134 lks.; burnt & rotted stub
8" Cedar bears S.38°E., 94 lks.; down & rotted uproot.
30" Cedar stub bears S.46°W., 66 lks.; missing.
30" burnt Cedar bears N.41°W., 210 lks.; point falls in cat road.
Restoration by Elliott State Forest Survey, 1939:
4" x4" x 4 ft. Hemlock post, found down and partially decayed, scribes visible.
18" Alder S.64°W., 46 ft.; missing, landing area.
Old line blazes found S., E., and W.
Set 1½" x 36" I.P. with bronze cap, from which a
48" Hemlock stump bears S.42°W., 109.2 ft. scribed T22S R11W S19 BT.
12" Cedar bears S.14½°E., 136.1 ft. scribed T22S R11W S20 BT.
12" Alder bears N.74°E., 64.9 ft. scribed T22S R11W S17 BT.
28" Fir bears N.43°W., 196.1 ft. scribed T22S R11W S18 BT. RS 359.
OSBF metal location poster on 14" Alder S.49°E., 18.0 ft.
Set 4"x4"x72" white painted cedar post 2 ft. SW of pipe.

Survey by Lloyd D. Smith - For: Oregon State Board of Forestry - May 1, 1991 - M 112-29

Found - OSBF 3" bronze cap dated 1960 on 1½" x 36" I.P., in place.
48" Hemlock stump S.42°W., 109.2 ft. in place.
12" Cedar S.14½°E., 136.1 ft., now 23" face closed, in place and bearing tree tag.
12" Alder N.74°E., 64.9 ft., now 16" bark scribes visible, in place, and bearing tree tag.
28" Fir N.43°W., 196.1 ft., now 27" x 3 ft. high stump, axe work visible, face rotted, in place, and bearing tree tag.

New Accessories:
11" Fir S.69°W., 42.6 ft. scribed "T22S R11W S19 BT" and bearing tree tag.
10" Fir N.2°W., 47.6 ft. scribed "T22S R11W S18 BT" and bearing tree tag.
White painted 4 x 4 cedar post S.29°W., 2.4 ft.