

PRIMARY CORNER DESCRIPTION Sec cor. for Secs. 17 & 18 only(North)

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 292, dated Aug. 7, 1878 - (DCSO records Vol. 5 Page(s) 1867)

Marked an Elder 5" dia. for the cor. to secs. 7, 8, 17 and 18, from which

- A Vine Maple 5" dia., bears N.10°E., 25 lks. dist.
- An Alder 8" dia., bears S.5°E., 40 lks. dist.
- An Alder 12" dia., bears S.65°W., 44 lks. dist.
- An Alder 12" dia., bears N.75°W., 73 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1959)

(Corner is .81 chs. N.89°50'W. of closing cor. for secs. 7 and 8)

At the old cor. to secs. 7, 8, 17 and 18, which is an Elder 7" dia., marked T22S S8 on NE.; R11W S17 on SE.; S18 on SW.; and S7 on NW. faces, with 4 notches on E. and S. sides, from which

- A Vine Maple 6" dia., bears N.10°E., 25 lks. dist. mkd. T22S R11W S8 BT.
- An Alder 16" dia., bears S.65°W., 44 lks. dist. mkd. T22S R11W S18 BT.
- An Alder 16" dia., bears N.75°W., 73 lks. dist. mkd. T22S R11W S7 BT.

The SE BT being gone

- A Cherry 12" dia., bears S.25°E., 59 lks. dist. mkd. T22S R11W S17 BT.

Elliott State Forest Boundary Survey - L. Beyers and E. Lough date ? 1941 - (DCSO Field Book 123 Page 11)

At sec.cor., Found the bearing trees and set a post 4"x4"x4 ft. to replace the corner tree which had been an Elder and had decayed. Set Post, from which

- A Cherry 12" dia., bears S.25°E., 40 ft.
- An Alder 12" dia., bears S.65°W., 30 ft.
- An Alder 12" dia., bears N.75°W., 50 ft.

Survey by S.O. and H.J. Newhouse - For: Cape Arago Lumber Co. - March 1957 - C.S. File 42/256 and M 1-54

Found orig. BTs:

- 12" Cherry, S.25°E., 38.9 ft., down and rotten.
- 16" Alder S.65°W., 29.0 ft., down and rotten.

(Cont. Next Page)

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Sec Cor for 17 & 18 only (North)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>16" Alder N.75°W., 48.2 ft., down and rotten. Set an Iron pipe for the corner, from which 18" Cherry S.33°E., 28.5 ft. mkd. S17 BT. New BT. 24" Alder S.89°W., 36.8 ft. mkd. S18 BT. New BT. No other trees available.</p>
<p>Fd. OK, August 1973 by Gibson, OSBF - M 51-28</p>
<p>Gary T. Smither for Scott Timber Co. Jan. - April 1997 - M 124-51</p> <p>-----</p> <p>Found - 1" outside dia. iron pipe set by Newhouse in 1957. No remaining evidence of bearing trees. New bearing trees - 12" Alder, SOUTH, 12.2 ft. to spike side center, bark scribe "T22 R11 S17 BT" 18" Alder, S.35°E., 26.4 ft. to spike side center, bark scribe "T22 R11 S17 BT" Note - Set 6 ft. steel post near monument.</p>
<p>Fd. Ok by Brent Bacon 2/2005 - M147-32</p>
<p>Jerry Estabrook - For: Moore Mill & Lumber Co. - 7/2020 - M177-34</p> <p>-----</p> <p>Found - A 1" outside dia. iron pipe per CS 42/256 & M1-54 with steel post near monument. A 17" Alder with bark scribing and tag bears South 12.2'. A 25" Alder with bark scribing and tag bears S.35°E., 26.4'.</p>