

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; & 31 & 32, T21-11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1859)

Set post cor. to secs. 5, 6, 31 and 32, from which
A Willow 5" dia., bears S.1°E., 36 lks. dist.
A Willow 5" dia., bears S.17½°W., 32 lks. dist.
These two trees are in same clump. No other trees near.
Post setting in natural mound about 2 ft. high by 4 ft. in diam.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 3 Page(s) 1255 (duplicate Pg. 1895)

At this point, I found remains of the mound at old cor. to secs. 5, 6, 31 and 32.
The post and bearing trees being gone, I re-established the cor. as follows:
Set a post 4 ft. long, 4" sq., 12" in the ground for cor. to secs. 5, 6, 31 and 32, marked T21S S32 on NE.; T22S S5 on SE.; R11W S6 on SW.; and S31 on NW. faces, with 5 notches on E. and 1 notch on W. edges, dug pits 18x18x12 ins. in each sec. 5½ ft. dist., and raised a mound of earth, 2 ft. high, 4½ ft. base, around post.

Elliott State Forest Boundary Survey - L. Beyers and E. Lough 1939 or 1941 ? - (DCSO Field Book 123 Page 18)

One 8" Spruce tree only tree for some distance in any direction at SW corner of wire pasture. Tide land to corner.

Douglas Co. Surveyors Office - James Byron, Deputy - John M. Powell and crew - Feb/June 1971 - C.S. File 56/5-2 & M 42-27

This cor. set from survey and lies in large field South of Hwy. #38.

Set Brass cap at cor. mkd: County Surveyors Office
T21S R11W S 31 | S 32
T22S S 6 | S 5
1971

Set steel fence post alongside brass cap.

Fd. OK, Jan. 1981 by R. Hintz - M 86-60

Fd. OK, June 1987 by OSHD - 0-1

(Cont. Next Page)

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; & 31 & 32, T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Corner found and used in BLM resurvey by Deborah M. Stephens and Harvey E. Wofford, under group #1521, surveyed April 1990 thru April 1995. (DCSO records Vol. 51 Page(s) 19591)

Fd. ok on Dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, & Richard Sanford, Surveying Technician, under Group #1644, surveyed April 1992/May 1996. (DCSO records Vol. 53 Page(s) 20189)

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 8/2/2024 - C.S. File 67/58-40

Found ok
BC found 1" below surface.
Fence post noted in 1971 DCSO report, not found.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
RTK MM pos.
N 313968.298 E -25522.070