

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GL0 survey by William Hall, Deputy Surveyor, under Contract #471, dated April 26, 1883 - (DCSO records Vol. 5 Page(s) 1870-71)

Set a cedar post 5 ft. long, 5" sq., 2 ft. in ground for cor. to secs. 5, 6, 31 and 32, marked T22S S32 on NE.; R11W S5 on SE.; T23S S6 on SW.; S31 on NW. faces with 5 notches on E. and 1 notch on W. edges, from which
A Cedar 40" dia., bears N.32°E., 85 lks. dist. mkd. T22S R11W S32 BT.
A Fir 40" dia., bears S.52°W., 50 lks. dist. mkd. T23S R11W S6 BT.
A Fir 60" dia., bears S.57°E., 298 lks. dist. mkd. T23S R11W S5 BT.
An Alder 8" dia., bears N.20°W., 46 lks. dist. mkd. T22S R11W S31 BT.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1877-78)

The old post being gone, I reestablished the cor. by setting a stone, 14x12x6 ins., 10" in the ground marked with 1 notch on the W. and 5 notches on the E. edges, from which
A Fir 60" dia., bears S.57°E., 298 lks. dist. mkd. T23S R11W S5 BT.
A Fir 50" dia., bears S.52°W., 50 lks. dist. mkd. T23S R11W S6 BT.
The NE. and NW. BTs., being gone, I marked
A burnt Fir 50" dia., bears N.87°E., 115 lks. dist. mkd. T23S R11W S5 & 6 BT.

GL0 survey by Albert N. Gould, Deputy Surveyor, under Contract #762, dated July 12, 1905 - (DCSO records Vol. 5 Page(s) 1978)

Cor. of secs. 5 & 6 which is a stone 14x12x6 ins., marked and witnessed as described by the Surveyor General.

Survey for Elliott State Forest Boundary Survey - 1933-34 - DCSO Field Book #124 Page 4

Found stone corner for secs. 5, 6, and one bearing tree which was
A burnt Fir 50" dia., bears N.87°E., 196 ft.
Marked for additional bearing trees:
An Alder 8" dia., bears N.80°W., 35 ft.
(Cont. Next Page)

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 236100

PRIMARY CORNER DESCRIPTION No. Sec. cor. for 5 & 6 only, T23-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Maple 8" dia., bears S.60°E., 44 ft.
A burnt Fir 36" dia., bears S.52°W., 33 ft.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Nov. 1958 - C.S. File 42/403-3

Original post, now missing, from which a:
40" Cedar bears N.32°E., 85 lks.; now missing, roots in place.
40" Fir bears S.52°W., 50 lks.; now rotted and burnt up-root.
60" Fir bears S.57°E., 298 lks.; now 54" burnt and rotted stub, scribed T23S R11W S5 remaining.
8" Alder bears N.20°W., 46 lks.; now missing.

Restored by Whipple, 1893:
Stone 14x12x6", found in place, 5 notches on the East, from which:

50" burnt Fir bears N.87°E., 115 lks.; now missing.
Built mound of stone around orig. stone, from which a:
11" Fir bears S.89½°E., 59.1 ft. scribed T23S R11W S5 BT
20" Fir bears S.37°W., 94.2 ft. scribed T23S R11W S6 BT.
5" Fir bears N.72°W., 10.5 ft. scribed RS 359.
Set 4"x4"x72" white painted cedar post 1.5 ft. SE of pipe.
OSBF metal location poster on above 5" Fir.

Fd. OK Sept. 1969 by A. Gibson, OSBF - M 38-53