TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 434700

PRIMARY CORNER DESCRIPTION M.C. No. bdy. Sec. 3

Alias _____ Description M.C. Left bank Dean Creek
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1857)

Left bank of creek. Measured across on log raft laying in creek.
Set M.P., from which
An Ash 6" dia., bears N.33°E., 94 lks. dist.
An Alder 8" dia., bears S.18°W., 89 lks. dist.
(Marks house bears N.25°E.)

BLM resurvey by John A. Farmer, Cadastral Surveyor, under Group #1421, surveyed Nov. 1987/Aug. 1994 (DCSO records Vol. 51 Page(s) 19282-83)

Point for the meander cor. of secs. 3 and 34 on the left bank of Dean Creek at proportionate distance; there is no remaining evidence of the original corner.
Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T21S
S 34
R11W ——— MC
S 3
T22S
1987

from which
A Spruce 9" dia., bears S.32°W., 90 lks. dist. mkd. X BT.
A Spruce 9" dia., bears N.20°W., 44 lks. dist. mkd. T21S R11W S34 MC BT.
Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

Fd. Ok on Dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, & Richard Sanford, Surveying Technician, under Group #1644, surveyed April 1992/May 1996. (DCSO records Vol. 53 Page(s) 20196-7)