

PRIMARY CORNER DESCRIPTION Sec. cor. for 10 and 11 only (South)

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1862)

Set a stone 20x10x6 for the cor. to secs. 10, 11, 14 and 15. Stone stands on top of large stone 4 ft. high. Also stone mound. No trees near for witness.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1908)

Intersect N. & S. line at cor. to secs. 10, 11, 14 and 15, which is a stone 10x6x2 ins. above mound, with 4 notches on S. and 2 notches on E. edges, with a mound of stone 1½ ft. high, 2 ft. base around stone.

Elliott State Forest Boundary Survey - L. Beyers and E. Lough - 1941 - (DCSO Field Book 120 Pages 3 and 43-44 and DCSO records, Field Book 122 Pg. 9)

Found a stone set in a mound of stone as described in field notes for cor. to secs. 10 and 11. Set Cedar post in a mound of stone by the stone set for corner, marked S10 on NW face, S11 on NE face.

Fd. notched stone in mound of stone - June 1963 - A. Gibson, OSBF - M 26-25

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Jan. 1971 - M 42-26

Section corner found. Original stone, 2 BTs. (No Record ?)