

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. cor. for 3 & 10 only (East side)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1861)

Set post for the cor. to secs. 2, 3, 10 and 11. No trees.
Built stone mound.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1904)

(Point of intersection is 9.24 chs. N.1°30'E.)
At old cor., I find remains of stone mound.
The old post being gone, I set a stone 20x12x10 ins., 2" in the ground for cor. to secs. 2, 3, 10 and 11, marked with 5 notches on S. and 2 notches on E. edges. Built a mound of stone 1½ ft. high, 2 ft. base around cor. No trees in limits
Pits impracticable.

Wilford N. Haines, #239 - Jan. 1956 - C.S. File 42/121

Found pile of stones.
Set a 36" Angle Iron with brass cap inscribed "Survey Point Wilford N. Haines 239", from which
12" Fir N.20°W., 26.0 ft.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - by Elbert Driver - Wit: Derald Timmons; Ron Witham - Filed Feb. 24, 1958 - C.S. File 42/340-5

Original post in stone mound, post missing and stone mound disturbed by uproot.

Resurvey by Whipple, 1893:

Stone 20x12x10", now missing.

Restored by Haines, 1956:

36" Angle iron with brass cap, found in place, 1" sheet metal cap, from which a

12" Fir N.20°W., 26.0 ft.; now 13", scribed "T22S R11W S3 BT" visible.

Restored:

Set 1½" x 36" galv. I.P. with 3" bronze cap marked "Oregon State Board of Forestry T22S R11W S3 S10 S11 1958 RS 359", over above angle iron, 33" in ground, in mound of stone, and from which a

11" Madrone bears N.51°W., 43.4 ft. scribed T22S R11W S3 BT.

28" Fir bears N.85°W., 53.5 ft. scribed RS 359.

(Cont. Next Page)

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec. cor. for 3 & 10 only (East side)

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

17" Fir stump bears S.50°W., 12.5 ft. scribed T22S R11W
S10 BT.

Set 4x4x48" white painted cedar post 1.0 ft. SW of pipe.
OSBF metal location poster on 10" Fir, N.81°E., 25.2 ft.