

PRIMARY CORNER DESCRIPTION A.P. on So. bdy. Sec. 36

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #612, dated April 28, 1893 (DCSO records Vol. 5 Page(s) 1884)

A point about 280 ft. above dry creek bed.
Set a stone 17x12x6 ins., 12" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which
 A burnt Fir 50" dia., bears N.20°E., 38 lks. dist. mkd. ¼ S BT.
 A burnt Fir 40" dia., bears S.41°W. 31 lks. dist. mkd. ¼ S BT.

GLO survey by Albert N. Gould, Deputy Surveyor, under Contract #762, dated July 12, 1905 - (DCSO records Vol. 5 Page(s) 1976)

¼ sec. cor. on N. bdy. sec. 1 which is a sandstone 17x12x6 ins. which I marked A.P., witnessed as described by the Surveyor General, which said witnesses I marked A.P. BT.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Nov. 24, 1971 - C.S. File 55/265 and M 45-3

Found - Original 17" x 12" x 6" stone, badly sluffed 4" x 10" stone found in place, from which a:
 50" burnt Fir bears N.20°E., 38 lks.; now 47" x 20 ft. high Fir snag in place.
 40" burnt Fir bears S.41°W., 31 lks.; now rotted root system, 30 ft. rotted log on ground.
Set 1½" x 35" galv. I.P. with 3" bronze cap mkd: "Oregon State Board of Forestry AP S1 T23S R11W 1971 RS359", 35" in ground, with original stone alongside, and from which a:
 28" Fir bears S.38½°E., 21.4 ft. to face, scribed T23S R11W S1 AP BT.
 25" Fir bears S.14°W., 11.0 ft. to face, scribed T23S R11W S1 AP BT, RS359.
Set 4"x4"x72" WPCP 2.3 ft. S.11°W. of corner pipe. OSFD metal location poster on 25" Fir S.14°W., 11.0 ft.

James M. McIntosh, Oregon Dept. of Forestry - Witness: Ralph C. Hall - 6/2011 - C.S. File 65/72-30

Found - Orig by Whipple, 1893: 17"x12"x6" stone (missing) from which:
 50" Burnt Fir N.20°E., 38 lks.; missing.
 40" burnt Fir S.41°W., 31 lks.; missing

continued next page

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 671100

PRIMARY CORNER DESCRIPTION A.P. on So. bdy. Sec. 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

RETRACEMENT by Gould, 1910, Fd sandstone, which he marked A. P., witnessed as described by the Surveyor General, said witness he marked A. P.B. T. (See above)

RESTORATION by Gibson, 1971: OSBF 1½"x36" galvanized iron pipe with 3" bronze cap (in place) from which a:

- 28" Fir S.38½°E., 21.4 ft.; now 33"x4 ft. high stump in place, face partially visible, added BT tag.
- 25" Fir S.14°W., 11.0 ft.; now 32"x5 ft. high stump, face closed, yellow metal location poster.
- 4"x4"x72" White painted cedar post S11°W 2.3 ft.; missing.

REWITNESSED from the above pipe and cap:

- Carsonite witness post S.05°E., 3.70 ft. to base.
- Carsonite witness post S.67°W., 2.35 ft. to base.

Magnetic variation set at 19° East.