

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias	Description

GLO survey by Simon B. Cathcart, Deputy Surveyor, under Contract #559, dated Nov. 15, 1890 - (DCSO records Vol. 5 Page(s) 2075)

Set a Hemlock post 4x4 ins., 5 ft. long, 2 ft. in ground for corner to secs. 29, 30, 31 and 32, mkd. T22S S29 on NE.; R12W S32 on SE.; S31 on SW.; and S30 on NW. faces, with one notch on S. and 5 notches on E. edges, from which
A Fir 36" dia., bears N.40°W., 27 lks. dist. mkd. T22S R12W S30 BT.
A Spruce 20" dia., bears S.50°E., 2 lks. dist. mkd. T22S R12W S32 BT.
An Alder 12" dia., bears S.72°W., 23 lks. dist. mkd. T22S R12W S31 BT.
A Fir 40" dia., bears N.70°E., 34 lks. dist. mkd. T22S R12W S29 BT.

Survey by Harvey Wilcox - For: Oregon Dept. of Fish and Wildlife and Douglas County - Dec. 1989 - M 109-50

Found - Root hole of a down Fir, no marks, bears N.40°W., 17.8 ft.
Root hole of a down fir, no marks, bears N.70°E., 22.4 ft.
Root hole of a rotten Spruce, no marks, bears S.50°E., 13.2 ft.
Set 3/4" Iron rod with 2" alum. cap in orig. position.
New BTs -16" Alder, bark scribed "T22S R12W S30 BT" with an X at BH and tagged, bears N.52°W., 18.56 ft.
20" D.Fir scribed "T22S R12W S29 BT" with an X at BH and tagged, bears N.19°E., 25.9 ft.
22" D.Fir scribed "T22S R12W S32 BT" with an X at BH and tagged, bears S.69°E., 17.7 ft.
24" D.Fir scribed "T22S R12W S31 BT" with an X at BH and tagged, bears S.44°W., 22.0 ft.

Fd. OK, Nov. 1992 by J. Minor - M 116-11