

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Simon B. Cathcart, Deputy Surveyor, under Contract #559, dated Nov. 15, 1890 - (DCSO records Vol. 5 Page(s) 2074-75)

-----  
Set Hemlock post 4" sq. 5 ft. long, 2 ft. in ground mkd. ¼ S on W. face for ¼ sec. corner, from which  
    A Spruce 60" dia., bears N.86°W., 33 lks. dist. mkd. ¼ S BT.  
    A Spruce 50" dia., bears N.75°E., 65 lks. dist. mkd. ¼ S BT.

Survey by John Minor - For: Menasha Corp. - Nov. 1992 - M 116-11

-----  
Found - Very rotten Spruce stump formerly 50", with scribe visible, N.75°E., 65 lks. (42.9 ft.) (Orig. BT.)  
        Very rotten Spruce stump, formerly 60", with scribe visible, N.86°E., 33 lks. (21.8 ft.) (Orig. BT)  
Set 1" x 36" I.P. with 2" brass cap stamped "T22S R12W ¼ S30 S29 1992 LS205". Cap set at distance intersect from faces of original BTs.  
New BTs -30" Spruce S.32°E., 7.3 ft. scribed ¼ S29 BT.  
          26" D.Fir N.32°E., 15.6 ft. scribed ¼ S29 BT.  
          29" Cedar N.01°W., 54.1 ft. scribed ¼ S30 BT.  
          28" Spruce N.39°W., 49.4 ft. scribed ¼ S30 BT.