

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 2000)

Set ¼ sec. post, from which
A Spruce 18" dia., bears S.38°W., 17 lks. dist.
A Spruce 20" dia., bears N.77°E., 10 lks. dist.

Survey by Robert M. Thompson - For: Edin Properties - April/Nov. 1973 - C.S. File 55/328 and M 51-65

Found - Orig. BT, 24" rotted Spruce stump with remains of old axe work and face at base, S.38°W., 11.2 ft.
18" 2nd growth Spruce growing in rotted remains of former O.B.T. Spruce stump, N.77°E., 10.6 ft.

Set 1¼" I.P.
Scribe "¼S 3683 BT" on:
29" Hemlock S.48°E., 16.6 ft.
17" Hemlock S.62°45'W., 20.4 ft.

Survey report by Les Roberts, LS #1039 - Jan. 20, 1989 - C.S. File 63/46-7(B)

Found - 1¼" Iron pipe set in 1973.
19" Hemlock stump S.45°E., 20.5 ft., scribe visible, (1973 BT. Rec. S.48°E., 16.6 ft.)
29" Hemlock stump S.63°W., 16.3 ft., scribe visible, (1973 BT. rec. S.62°45'W., 20.4 ft.)
Set 60" alum. post with land survey monument sign attached to, beside 1¼" iron pipe. Painted all BTs red.
Corner lies on a East slope about 150 ft. East of road.