

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 2003)

-----  
Set ¼ sec. post, from which  
A Spruce 20" dia., bears S.18½°W., 67 lks. dist.  
A Spruce 18" dia., bears N.89°W., 18 lks. dist.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy, Crew: Greg Quibell; Karen Reed; John Powell - April 12, 1982 - C.S. File 61/30-24

-----  
Found - Orig. 20" now 34" badly rotted Spruce stump 6 ft. tall. Found reverse scribed "BT" on pitched up face.

No trace of orig. 18" Spruce found.  
At record bearing and distance from orig. 20" Spruce (N.18½°E., 44.2 ft.) I SET a 1" x 30" I.P. with brass cap attached, protruding 7" out of ground. Cap is mkd: "Douglas County Surveyors Office T22S R12W S8 S17 ¼ 1982".

New BTs -30" double Spruce with scribed "¼ S8 CS BT" in double blaze bears N.16°E., 17.5 ft.  
20" Spruce scribed "¼ S8 CS BT" in double blaze bears N.67°E., 32.4 ft.  
17" Spruce scribed "¼ S17 CS BT" in double blaze bears S.23°E., 27.5 ft.  
15" Fir scribed "¼ S17 CS BT" in double blaze bears S.53°W., 19.6 ft.

Cor. Fd. OK, June 16, 1987 by Les Roberts - C.S. 63/46-8(C) "Set 60" alum. post with land survey monument sign attached to, beside brass cap. Painted all BTs red. Corner lies on SW slope about 350 ft. South of ridge. Ridge bears N.60°W. and S.60°E.

Fd. Ok by John Bentley, Oct. 1995 - M 123-4