

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2052)

Set a Hemlock post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 20, 21, 28 and 29, mkd. T22S S21 on NE.; R12W S28 on SE.; S29 on SW.; S20 on NW. faces, with 2 notches on S. and 4 notches on E. edges, from which

A Spruce 48" dia., bears N.70°E., 5 lks. dist. mkd. T22S R12W S21 BT.

A Hemlock 6" dia., bears S.35½°E., 44 lks. dist. mkd. T22S R12W S28 BT.

A Fir 40" dia., bears S.18½°W., 31 lks. dist. mkd. T22S R12W S29 BT.

A Hemlock 15" dia., bears N.43½°W., 25 lks. dist. mkd. T22S R12W S20 BT.

Douglas County Surveyors Office - L.E. Monrean, Deputy - K. Reed; S.J. Flause; F. Silagy; V. Woodral, crew - June 25, 1979 - C.S. File 60/34-1

Found - A 48" Spruce now a 60" dia., stump, bears N.70°E., 3.3 ft. with scribing "12 W S21" visible. (orig.)
A Hemlock stump badly rotted, bears S.35½°E., 27.3 ft., visible scribed "S28". (orig.) (rec 29.0 ft.)
40" Fir now a 42" dia. stump, bears S.21½°W., 20.5 ft. (Rec. S.18½°W.) Visible scribing "2 W 29" on 42" stump (orig.)

Set a 1" x 36" I.Pipe with brass cap mkd. "Douglas County Surveyor T22S S20 S21 S29 S28 R12W 1979" at proper position.
New BTs -14" D.Fir bears S.62°W., 11.8 ft. dist. scribed "S29 T22S R12W CS BT" in a double blaze.

15" Hemlock scribed "S20 T22S R12W CS BT" in a double blaze, bears N.37½°W., 16.8 ft.

16" D.Fir scribed "T22S R12W S21 CS BT" in a double blaze bears N.12°E., 27.1 ft.

16" Spruce bears S.19°E., 6.1 ft. scribed "T22S R12W S28 CS BT" in a double blaze.