

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2048)

Set a Hemlock post 4 ft. long, 6" sq., 24" in the ground, for cor. to secs. 16, 17, 20 and 21, mkd. T22S S16 on NE.; R12W S21 on SE.; S20 on SW.; S17 on NW. faces, with 3 notches on S. and 4 notches on E. edges, from which

- A Cedar 15" dia., bears N.79½°E., 46 lks. dist. mkd. T22S R12W S16 BT.
- A Hemlock 12" dia., bears S.19°E., 11 lks. dist. mkd. T22S R12W S21 BT.
- A Spruce 40" dia., bears S.38°W., 27 lks. dist. mkd. T22S R12W S20 BT.
- A Spruce 36" dia., bears N.33°W., 28 lks. dist. mkd. T22S R12W S17 BT.

Douglas County Surveyors Office - Janet Lundeen, Deputy - R. Smith and S. Flause, Crew - April 29, 1986 - C.S. 62/43-F and M 101-18

Found - 40" Spruce now 45" stump, 8 ft. high bears S.38°W., 19.5 ft. (Rec. S.38°W., 17.8 ft. face meas.) No scribing found.
36" Spruce now a 44" stump 5 ft. high bears N.33°W., 20.0 ft. (Rec. N.33°W., 18.5 ft. face meas.) No scribing found.

Set 1" (1 3/8" O.D.) x 32" pipe with 2 3/8" brass cap marked:
Douglas County Surveyors

T 22 S
S 17 | S 16
S 20 | S 21
R 12 W
Office

Cap protrudes 4" above mound of sandstone.
New BTs -6" Red Cedar bears S.20¼°W., 5.9 ft. double blazed and scribed "T22S R12W S20 CS BT".
30" D.Fir bears N.56°W., 11.1 ft. double blazed and scribed "T22S R12W S17 CS BT".
12" Red Cedar bears S.54¼°E., 27.0 ft. double blazed and scribed "T22S R12W S21 CS BT".
17" Hemlock bears N.68°E., 21.4 ft. double blazed and scribed "T22S R12W S16 CS BT".
(See CS 62/43 for further procedure notes and topog calls.)

Fd. OK, March 1992 by H. Wilcox - M 115-4