

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 27 and 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2044)

-----  
Set an Alder post 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on N. face. Dug pit 18x18x12 ins. E. and W. of post and 5 1/2 ft. distant, raised a mound of earth 1 1/2 ft. high and 3 1/2 ft. base alongside.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - March 20, 1970 - M 33-79

-----  
Reset by proportionate measurement.  
Set OSBF 1 1/2" x 36" galv. Iron pipe with 3" bronze cap, from which  
36" Spruce N.82 1/4°W., 7.5 ft. with yellow metal location poster.  
16" Fir S.15 1/2°E., 17.3 ft. "RS 359".  
4x4x72" white painted cedar post, NE., 1.2 ft.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - March 1970 - Correction map filed Nov. 10, 1972 - M 42-76

-----  
1/4 corner reestablished.  
Set OSBF 1 1/2" x 36" G.I.P. with bronze cap, 34" in ground, from which  
37" Spruce N.73°W., 3.8 ft. with yellow metal location poster.  
16" Fir S.28°E., 19.2 ft. with yellow metal location poster.  
4x4x72" white painted cedar post N.65°E., 1.6 ft.

Fd. OK, June 1987 by M. Hoyer - M 104-31