

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 3; and S34, T21-12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1264)

Set gr. sec. post, drove charred stake, raised mound with trench as per instructions.

Douglas Co. Surveyors Office - James Byron, Douglas Co. Surveyor - For: Warren Waggoner - Aug. 9, 1956 - C.S. File 47/129

Position of corner established from tie shown on Amended Plat of R.R. Addition and monument at 10th and Winchester Sts. used for control. Corner falls in street so no monument set. Bearing Objects are chisled "+" in concrete on East abutment of bridge, and bears S.35°16'W., 19.1 ft.; S55°28'W., 159.0 ft.
NW corner of Texaco Service Station bears N.59°22'E., 236.3 ft.
(County Surveyors brass cap set in 1956, recorded Nov. 1967)

Survey by Glenn Baughman - For: Lillebo & Holliday - April 1973 - M 49-41

Found - Chisled "+" in concrete on East abutment of bridge bears S.35°16'W., 191.1 ft.
Chisled "+" in concrete on East abutment of bridge bears S.55°28'W., 159.0 ft.
Set brass cap from found bearing objects, per telephone conversation from Eugene Bloom, 11/8/73