

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2028)

-----  
Set a Chittem post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 26, 27, 34 and 35, mkd. T22S S26 on NE.; R12W S35 on SE.; S34 on SW.; S27 on NW. faces with 1 notch on S. and 2 notches on E. edges, from which

An Alder 8" dia., bears N.59°E., 45 lks. dist. mkd. T22S R12W S26 BT.

An Alder 6" dia., bears S.58°E., 26 lks. dist. mkd. T22S R12W S35 BT.

An Alder 4" dia., bears S.62°W., 310 lks. dist. mkd. T22S R12W S34 BT.

A Fir 30" dia., bears N.89°W., 260 lks. dist. mkd. T22S R12W S27 BT.

-----  
Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Marcy 20, 1970 - M 33-79 -

-----  
Sec. corner reestablished.

Set OSBF 1½" x 36" galv. I.P. with 3" bronze cap., from which 21" Fir S.52°W., 12.9 ft. with yellow metal location poster.

29" Myrtle, double trunk, S.81°E., 34.0 ft.

16" Fir N.10°W., 24.3 ft. "RS 359"

4"x4"x72" white painted cedar post 1.0 ft. from cor., SW.

-----  
Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Correction survey filed Nov. 10, 1972 - M 42-76

-----  
Set OSBF 1½" x 36" G.I.P. with bronze cap 34" in ground, from which

15" Fir N.2½°W., 29.4 ft. "RS 359".

23" Fir S.15½°W., 8.3 ft., YMLP.

14" Myrtle, in clump of three, S.84°E., 41.3 ft.

11" Fir N.87 3/4°E., 60.9 ft.

4x4x72" white painted cedar post, West 1.4 ft.

-----  
Fd. Ok by C. Mulkins 7/2006 - M151-16