

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2029)

-----  
Set a Cedar post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S on N. face, from which  
A Spruce 8" dia., bears S.30°W., 40 lks. dist. mkd. ¼ S BT  
A Red Fir 24" dia., bears N.32°W., 6 lks. dist. mkd. ¼ S BT.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - May 22, 1970 - C.S. File 55/154-3

-----  
Found orig. Cedar post, missing, from which:  
8" Spruce bears S.3°W., 40 lks.; now missing.  
24" Fir N.32°W., 6 lks.; now 60" stump, in place, scribe visible.  
Restoration by Haines, (no record found, date unknown. In telephone conversation, Mr. Haines stated he had filed this corner.) (Per DCSO, no record found.)  
1" Tee bar, found in place, from which  
40" Hemlock S.8°W., 24.8 ft. to face, in place, face open, scribes visible.  
53" Hemlock bears N.61°W., 48.7 ft to face, in place, face closed.  
Set 1½" x 36" galv. I.P. with 3" bronze cap mkd. "Ore. St. Bd. of Forestry ¼ S26 S35 1970 RS 359", 34" in ground, over 1" T.Bar and from which:  
46" Fir bears N.31°W., 51.8 ft. to face, scribed ¼ S26 BT RS 359.  
4x4x72" White painted cedar post 1.2 ft. N.22°W. of corner pipe.  
OSBF metal location poster on 46" Fir BT, N.31°W., 51.8 ft.

Fd. OK, Jan. 1986 by L. Smith - M 100-38