

PRIMARY CORNER DESCRIPTION West 1/4 Cor. for Sec. 36 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Charles A. Slang, Deputy Surveyor, under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 2102)

Set a Cedar post 3 ft. long, 10" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S36 on E. face, from which

- A Chittem 25" dia., bears S.81°30'E., 45 lks. dist. mkd. 1/4 S36 BT.
- A Fir 54" dia., bears S.10°20'E., 368 lks. dist. mkd. 1/4 S36 BT.

No tree in the NE available.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Restored by Wm. Metcalf - April 1975 - M 55-73

Found 2 BTs, Stephens 1952.

To witness corner, set a OSBF 1 1/2" x 36" galv. I.P. and 3" bronze cap 42" in the ground, S.04°52'37"E., 54.5 ft. from which

- 21" Alder N.38°E., 71.4 ft. "RS 359"
- 12" Alder S.34°E., 168.8 ft.

4x4x72" white painted cedar post S.15°E., 2.7 ft. with yellow metal location poster.

Wit. Cor. Fd. OK, Jan. 1986 by L. Smith - M 100-38

Survey by Les Roberts - For: I.P. Co. - Feb. 21, 1989 - C.S. File 63/91 and M 107-66

1/4 Corner report only

Found - 23" Alder N.77°E., 23.4 ft., no marks, 1952 BT.
(Rec. N.77°E., 23.4 ft. (No record in Douglas County - probably filed in Coos County)

Corner falls in Murphy Creek. No monument found. Witness corner falls S.5°E., 54.5 ft.