

PRIMARY CORNER DESCRIPTION Sec. cor. for 23 & 26 only (East)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #323, dated May 26, 1879, - (DCSO records Vol. 5 Page(s) 2017)

Marked a Maple 8" dia. for the cor. to secs. 23, 24, 25 and 26, from which

- A Maple 8" dia., bears N.50°E., 12 lks. dist.
- A Fir 10" dia., bears S.65°E., 40 lks. dist.
- An Alder 36" dia., bears S.30°W., 39 lks. dist.
- An Alder 36" dia., bears N.89°W., 70 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2023)

At the cor. to secs. 23, 24, 25 and 26, which is a Maple 8" in dia., now cut down, with only the stump remaining; I replace the same by setting a Fir post, 4 ft. long, 4" sq., 24" in the ground, mkd. T22S S24 on NE.; R12W S25 on SE.; S26 on SW.; S23 on NW. faces, with 2 notches on S. and 1 notch on E. edges, from which

- Stump of Alder 36" dia., bears S.30°W., 39 lks. dist. mkd. BT.
- Stump of Alder 36" dia., bears N.89°W., 70 lks. dist. mkd. BT.
- Stump of Maple 8" dia., bears N.50°E., 12 lks. dist. mkd. BT.
- A Spruce (given as Fir) 10" dia., bears S.65°E., 40 lks. dist. mkd. S25 T22S R12W BT.

in accordance with the description in the field notes furnished me. In place of the Maple, I give as additional bearing tree:

- A Fir 48" dia., bears N.2°E., 1.67 chs. dist. mkd. T22S R12W S24 BT.

No other trees within limits W. of corner.

GLO survey by Charles A. Slang, Deputy Surveyor, under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 2099)

Intersect the point for old cor. of secs. 23 and 26, I destroy all trace of this old cor. and reestablish at the same point as follows:

Set a sandstone 18x12x10 ins., 12" in the ground for cor. of secs. 23 and 26, mkd. with 2 notches on S. and 1 notch on E. edge, from which

- A Fir 14" dia., bears S.60°30'W., 294 lks. dist. mkd. T22S R12W S26 BT.

(Cont. Next Page)

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 23 & 26 only, (East)

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

An Alder 10" dia., bears N.54°15'W., 282 lks. dist. mkd.
T22S R12W S23 BT.

Survey by Arnold G. Gibson - For: Oregon State Board of Forestry - Lloyd D. Smith, transitman - Aug. 1, 1969 - C.S. File 55/101-11

Orig. Post and BTs missing.

Creek, 20 lks. wide, course N.20°W., bears S.89°48'W., 1.75 chs., in place.

Retracement by Thiel, 1889: Fir post, now missing, from which a

48" Fir bears N.2°E., 167 lks.; now 65" stump, in place, evidence of destroyed face remaining.

Bottom, S.15°E. and N.15°W. bears South .50 lks.; in place
Creek, 5 lks. wide, course N.20°W., bears South 140 lks.; in place.

Leave bottom, bears South 300 lks.; in place.

Resurvey by Slang in 1910: 18x20x10 in. sandstone, missing, from which a:

14" Fir bears S.60½°W., 294 lks.; missing, point falls in road.

10" Alder bears N.54½°W., 282 lks.; missing, point falls in road.

Set 1" x 36" galv. Iron pipe with 3" bronze cap mkd: "Ore. St. Bd. of Forestry T22S S23 S26 R12W S24 1969 RS 359", 34" in ground, and from which a:

10" Alder bears N.85½°W., 38.9 ft. to face, scribed T22S R12W S23.

9" Alder bears S.3½°W., 54.0 ft. to face; scribed T22S R12W S26.

Set 4x4x72" white painted cedar post 2.4 ft. West of corner pipe.

OSFD metal location poster on 10" Alder, N.85½°W.

Fd. OK, May 1991 - M 113-35 A&B