

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 1995)

-----  
Set post corner of secs. 13, 14, 23 and 24, from which  
An Alder 24" dia., bears N.23°W., 46 lks. dist.  
An Alder 15" dia., bears S.10°W., 22 lks. dist.  
An Alder 24" dia., bears S.1°E., 31 lks. dist.  
An Alder 15" dia., bears N.89°E., 37 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 2016)

-----  
Set a post for corner secs. 23, 24, 13 and 14, from which  
A Cedar 12" dia., bears N.50°E., 35 lks. dist.  
An Alder 30" dia., bears S.61°E., 60 lks. dist.  
An Alder 30" dia., bears S.34°W., 54 lks. dist.  
A Cedar 36" dia., bears N.4°W., 52 lks. dist.

GLO survey by Charles A. Slang, Deputy Surveyor, under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 2096 and 2097-98)

-----  
The old cor. of secs. 13, 14, 23 and 24, which is almost destroyed.  
I destroy all trace of the old cor. and reestablish it at the old point as follows:  
Set a sandstone 20x15x10 ins., 15" in the ground for cor. of secs. 13, 14, 23 and 24, marked with 3 notches on S. and 1 notch on E. edge, from which  
An Alder 15" dia., bears N.27°E., 31 lks. dist. mkd. T22S R12W S13 BT.  
An Alder 38" dia., bears S.48°E., 5 lks. dist. mkd. T22S R12W S24 BT.  
An Alder 26" dia., bears S.45°W., 50 lks. dist. mkd. T22S R12W S23 BT.  
An Alder 30" dia., bears N.65°W., 103 lks. dist. mkd. T22S R12W S14 BT.

Survey by Clifford A. Stephens - For: O.B. Walker - July 14, 1966 - (Filed June 1968) - C.S. File 55/80 and M 33-35

-----  
At the point 66 ft. North of the creek, I drove 3/4" copper pipe, 4 ft. long, 3½ ft. into the ground for sec. corner. (The ground being soft, I found a piece of old 1" water pipe 7 ft. long which drive alongside the copper pipe), from which  
An Alder 10" dia., bears N.28°E., 22.3 ft.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>A Spruce 9" dia., bears N.59°W., 38.5 ft.          An Alder 10" dia., bears S.5°W., 34.2 ft.          (The Alders are bark scribed, location tag on face)          Corner is located on the right side of a narrow draw bearing N-S at this point, and 348 ft. South of the edge of the timber.</p>
<p>Survey by Bruce A. Shaner - For: Moore Mill &amp; Lumber Co. -          Feb. 1987 - RM 3-66 A&amp;B          -----          Found - 3/4" copper pipe with a rusty 1½" iron pipe          alongside.          18" Alder bears N.28°E., 22.3 ft. with bark scribing          visible.          10" Spruce bears N.53°W., (Rec. N.59°W.) 38.5 ft.,          has old face.          18" Alder bears S.5°W., 34.2 ft., bark scribing          visible.          BT of no record: 16" Alder bears S.61°E., 36.6 ft.,          bark scribing visible.          Corner is in bottom of draw with stream, approx. 300 ft.          above pasture.</p>
<p>Fd. OK, May 1991 - M 113-35 A&amp;B</p>
<p>Brent Bacon - For: Menasha Forest Products - 1/2007 - M152-12          -----          Found - The SW corner of sec. 13 has been covered by a          slide. A 3 ft deep search hole was dug until it          started filling with water. No monument was found          but there was a metal detector return in the          bottom of this hole. A best fit position from the          metal detector return and the fd BTs was used to          reestablish this corner.          Fd. BTs- 14" rotten Alder stump, S.62°E., 36.3'          14" rotten Alder stump, S.4°W., 33.0' (Rec. 34.2')          23" spruce, N.57°W., 38.1, healed face.          Set - 1½x30" iron pipe with 2" brass cap marked: "T22S          R12W S14 S13 S23 S24 2006 LS2869"          6" Alder, N.4°E., 16.9', bark scribed "BT"</p>
<p style="text-align: right;">2</p>