

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 1995)

Set ¼ sec. post, from which
A Hemlock 6" dia., bears N.85°W., 24 lks. dist.
A Hemlock 4" dia., bears S.50°E., 5 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 2015)

Set Fir post for ¼ sec. corner, from which
A Hemlock 12" dia., bears N.65°E., 13 lks. dist.
A Fir 40" dia., bears N.60°W., 35 lks. dist.

GLO survey by Charles A. Slang, Deputy Surveyor, under Contract #793, dated Feb. 17, 1910 - (DCSO records Vol. 5 Page(s) 2096 and 2097)

The old ¼ sec. cor., which is nearly destroyed, the old post is missing.
I destroy all trace of this old cor. and reestablish at the same point as follows, because the marks were no longer readable on the bearing trees and the post was missing.
Set a Hemlock post, 3 ft. long 10" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ S14 on W. and 13 on E. face, from which
A Hemlock 26" dia., bears N.65°E., 13 lks. dist. mkd. ¼ S13 BT.
A Fir 40" dia., bears N.62°W., 35 lks. dist. mkd. ¼ S14 BT.
From this cor., the Sampson Post Office bears West about 35.00 chs. dist.

Survey by Clifford A. Stephens - For: J. Lightfoot - May/June 1965 - C.S. File 51/321 and M 22-72

Set new Red Cedar post for the ¼ corner, from which
26" Hemlock bears N.65°E., 8.6 ft., is tipped over.
40" Fir bears N.62°W., 23.1 ft., scribing visible.

Fd. OK, April 1976 by D. Stuntzner - M 60-22

Survey by Robert B. Ward Jr. - For: Champion International Corp. - Feb. 24, 1977 - C.S. File 58/139 and M 65-4

Found - A Cedar post set by Stephens in 1965.
Orig. BT, now a 40" Fir stump, bears N.62°00'W.,
23.1 ft. (Cont. Next Page)

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

The Hemlock is gone.
From the above mentioned BT, I SET a 3/4" x 36" galv. I.P. with brass cap, from which
 A 14" hemlock bears N.35°00'W., 19.4 ft.
 A 6" hemlock bears N.50°30'E., 39.6 ft.
I replaced the post set by Stephens with a 4"x4"x6 ft. cedar post. This post bears S.72°00'E., 2.2 ft. from my brass cap iron pipe.

Fd. Ok by Corey Woodruff, 2/2006 - M149-65

Brent Bacon - For: Menasha Forest Products - 1/2007 - M152-12

Found - 3/4" iron pipe with 3" brass cap MKD: "T22S R12W 1/4 S14 S13 1977 PLS1091"
 44" fir stump, N.59°W., 23.1'
 17" hemlock, N.51°E., 39.6', healed face.
 17" hemlock, N.35°W., 19.2', healed face
 Wood post with sign bears N.79°E., 2.4'